REMONUMENTATION LIBER 15150 rc 485

Dec 1594316418

		MAY -	1 1995	I AND CORNE	R RECORDATION CER	TIFICATE	ACT 345, P.A. 1990	
		,		Filing Require	ment of Act 74. Mich.	P.A. 1970 ^{APPRO}	oved on: 9-21-44 and county remonumentation	
Fo	corners in Oakland	COMN	IISSION	0112 011) OAKLA	AND COUNTY REMONUMENTATION PEER GROUP COMMITTEE	
_	(County)		Loca	ated in: Twp.	Corner Code ##	\$ 7.66	NISCELLANEOUS RECORDING	
1.	Public Land Su	urvėy		<u>10E</u>	I-11	\$ 2,00		
				R R		15 DEC	94 10:41 A.M. RECEIPT# 25B	
			T	R		PAID LYNN D	RECORDED - DAKLAND COUNTY . ALLEN, CLERK/REGISTER OF DEEDS	
2.	Property Control in Section	olling		R R			DK - T. SMITH	
3.			S T.	R		Register	of Deeds Stamp & File Number	
	Property in Sec	C.	S T	R				
4.	Lot No	, Red	corded Plat			A	BCDEFGHIJKL	
5.	Private Claims						6 5 4 3 2 1 -	
			>			3		
. 1	Auston K. Ke	ennedv	: 6'al-1 a	A1	gust 1 1994	4 L	- 7 - 4 - 8 - 4 - 9 - 4 - 10 - 4 - 11 - 4 - 12 -	
do	nereby certify that	t under requi	rements of P.A	N. 74, Michigan P.A. o	of 1970, the corner points med	ntioned 6	18 17 16 15 14 13	
ın i Cur	ines 1 and 2 aborers to the second and 2 aborers to the se	ve were in d rvev instruct	onformance vitions of the Ur	with regulations and nited States Departr	I rules therefore as required ment of the Interior, Bureau i	d in the of Land		
Ma	nagement or by a c	decree of a C	ourt of Law ar	id/or that the corner	points mentioned in lines 3,	4 and 5 8	19 20 21 22 23 24	
abo Co	ive were in confor urt of Law; estal	mance with blished, re-	the rules of th established,	e Michigan Board of monumented, ire-m	Land Surveyors or by a Deconumented, recovered, for	und as "	-}	
	ressed below:			.	d	10 L	30 29 28 27 26 25	
NO	TE: Not more on this ce		ners, all in t	ne same town and	d range, may be recorde	12	31 32 33 34 35 36	
					or subsequent restoration	13 L		
	3.) 1985-Bucker 4.) 1989-Bongio 5.) 1990-Newman 6.) 1989-Bongio	field, P.S ovanni, P.S 1, P.S. #24 ovanni, P.S	. #10868; LC . #24586; LC 507; LCRC L. . #24586; Su	RC L.11191, Pg.419 11604, Pg.641 - Fr rvey L.11217, Pg.6	- Fnd 1/2" Iron in Monu 9 - Fnd Iron Rod nd Iron in Monument Box 582 - Fnd Iron Rod, used	same wit as 198		
3,	•				pplied in restoring or ree			
	has a cond	Kennedy Surveying, Inc Kennedy, P.S. #17623 - Fnd 1/2" Iron in a Monument Box in the centerline of Silver Bell Road, which has a concrete surface and 240' East of the entrance to Eagle Valley Disposal.						
	Witnesses	Witnesses from LCRC #3 were used to recover and verify the location of the found 1/2" Iron in a Monument Box.						
	I accepted	the found	1/2" Iron R	od in a Monument 1	Box as the best evidence	of the original	corner position.	
					e e		\hat{r}_{i}^{g}	
							A to be to the second	
C.	Description of	description of monument for corner and accessories established to perpetuate locating the position of the corner:						
	I-11 I replaced the found 1/2" Iron Rod with a 5/8" x 24" Iron rod w/2" diameter brass cap stamped Oakland County Renonumenta							
	PS #17623 in a existing Monument N14 E 62.03' Set PK & Remon. Wash N75 E 221.54' Set PK & Remon. Wash			BOX. her SK face Power	Pole		THE OF MICHIGA	
				sher South face P	ower Pole		HUSTON	
				sher South face Powersher SE face Powe			HUSTON KENNEDY PROFESSIONAL	
	The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available expenses position of the original corner.							
		I		•			ROFESSIONAL	
نان نان	ned by	less &	100		Date _	December	3, 1994	
oig S	HOU DY	n Linaras	N.17623	U			MAIGUREAN STATE BRAUN RE LANG SUBVEYRAS LAN 98 1	
SUI	veyor's Michiga	an License	190.			FORM APPROVED BY	MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28." REVISED MAY 14. REVISED JAN	

The second of th