## SURVEY & REMONUMENTATION

LIBER 14960rc 095

242425

	re-x	- X
7.00	MISCELLANEOUS	RECORDIN
	CENTAL INCREATATE	

YARR		4	1995	
MAY	•	ì	199	Э

\_ , Recorded Plat

Lot No. 5. Private Claims \_ LAND CORNER RECORDATION CERTIFICATE 2.00 NETWORKEN AND LUN

Fo		y - 1 1995	Filing Requirement	ent of Act 74, Mich.	
	Oakland CC	1012 <u>21MMC</u>	Located In: Orion Township	Corner Code ##	LYNN D. ALLEN, CLERK/REGISTER OF DEEI
1.	Public Land Surv	rey	T <u>4 N R 10 E</u> T R	K-3	
		-	T R T R		Compliance with ACT 345, P.A. 1999
2.	Property Controll in Section	-	TR TR		APPROVED ON: 1-5-94  QANLAND COUNTY REMONUMENTATION
3.	Miscellaneous Property in Sec.	. <del></del>	T R _T R		Regist <del>的原料Deads Stant Strife</del> Number
				•	

I. Huston K. Kennedy , in a field survey on , <sub>19</sub> \_93 November 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

11 13

Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S.; Set Post; 36" White Oak N29 1/2°E 53 Lnks; 6" White Oak S67°W 98 Lnk 1973-Hubbell, P.S. #12022; LCRC L.6701, Pg.45-46 - Fnd concrete monument 1983-Kapelczak, P.S. #24598; LCRC L.8335, Pg.575 - Fnd concrete monument

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - 1993 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd a square concrete monument with a 3/4 Iron Pipe. There is a tree line extending to the South.

Witness points from the 1973 LCRC and 1983 LCRC were found and they were used to recove and verify the found square concrete monument with 3/4" Iron Pipe.

I accepted the found square concrete monument as the best evidence of the original corne position.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- I replaced the found square concrete monument with 3/4" iron pipe with a 4" diameter concrete monument 36" long with a 2" diameter cap stamped Oakland County Remonumentation "17/22" OF MICE. ATE OF MICHOEL

N15°E-45.81 ft-Set PK/Remon. Tag West face 8" Maple N85°W-5.38 ft-Set PK/Remon. Tag SW face 10" Spruce S45°W-7.33 ft-Set PK/Remon. Tag NW face 10" Spruce Due South-55.46 ft-Set PK/Remon. Tag East face Power Pole

The selected location is accepted by me and is generally accepted by P as the best available evidence of the position of the original position \_\_\_\_\_ Date \_\_\_\_ <u>June 22, 1994</u> Signed by A

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SERVEYORS, JA YEYORS, JAN. 28, 197 REVISED MAY 14, 197: REVISED JAN., 198

HUSTON KENNEDY

AND MILLIONS

17623 Surveyor's Michigan License No. (\_\_