Surveyor's Michigan License No._

LIBER 17634 PC847

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ş
29
2
1
$\mathbf{\omega}$

Oakland Located in Orion Twp. Corner Code #	\$ 9.00 HISCELLANEOUS RECORDING 3 2.00 REHONUMENTATION
(County)	29 SEP 97 12:45 P.M. RECEIPT# 14780
1. Public Land Survey	PAID RECORDED - DAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS Compliance with
2. Property Controlling S T R	ACT 345, P.A. 1990
in Section S T R	APPROVED ON: 8-28-97 15
3. Miscellaneous S T R	OAKLAND COUNTY REMONEMENTATION PEER GROUP COMMITTEE
Property in Sec. S TR	Register of Deeds Stamp & File Number
L	Trogration of Books Ottaling at the Hallings
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K L M
	2 6 5 4 3 2 1 1
	3
1, Iluston K. Kennedy , in a field survey on 8-8 , 19 97 do hereby state that under	4 - 7 - 8 - 9 - 10 - 11 - 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	6 18 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10-30-29-28-27-26-25
	11
	12 31 32 34 35 36
	13
1817-GLO Wampler, D.S.; Set Post 6" White Oak N18°W 21 Links; 18" White Oak S27°E 31 1.) 1943 McAlpine, PS \$1015; Unrecorded Survey - Fnd post, no witnesses	Links
	™.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corners. Surveying, Inc Kennedy, PS \$17623 - The only evidence that I was able the East, West, North and the intersection is at a 24" Oak.	rner: to recover a existing fence line extending to
HOW THE CORNER WAS RECOVERED	Comment of the Company of the Compan
I recovered the corner by setting a reference corner in the existing East-West f was held as the corner.	·
Field measurements see back side of LCRC	900 FILE
C. Description of monument for corner and accessories established to perpetuate locating the po	asition of the corner
L-9 I set a 4" diameter Concrete Monument 36" long with 1/2" Iron Rod w/2" diameter bra PS #17623 as a REFERENCE CORNER 6.80 feet East of the corner. Due West 6.80' Set PK & Remon Washer North face 24" Oak	ass cap stamped Oakland County Remonumentation
S56°E 34.88' Set PK & Remon Washer SE face 11" Cherry	METINE OF MICHIGA
N84°W 27.23' Set PK & Remon Washer North face 29" Oak N47°W 25.91' Set PK & Remon Washer NE face 40" Twin Oak	HUSTON 4
The selected location is accepted by me and is generally accepted by Professional Supposition of the original corner.	rveyors as the best available of the
	The state of the s
Signed by And Hard	9-79-97

SURVEY & REMONUMENTATION

APR 0 7 1998

LIBER 17634 PG848

SECTION

PIELD NEASUREMENTS BETWEEN

<u>L-9 to K-9</u>

GLO = 39.16 chains or 2584.56 Ft. No sidwell or plat distances GPS-MEA = 2664.28 Ft.

L-9 to N-9

GLO = 39.16 chains or 2584.56 Ft. Sidwell distance = 2687.86 Ft. (Section 24) GPS-MEA = 2687.23 Ft.