

UNI 19758P(497

	LAND	CORNER RECORDATION	CERTIFICATE	106311
For corners in	Filing	Requirement of Act 74, Mi	ch. P.A. 1970IBER	19758 PAGE 497
i or corrects in			, \$7.00 8	ISC RECURDING
Oakland (County)	Located In:	Corner Code#	03/30/1 PAID	EMONUMENTATION 999 01:03:22 P.M. RECEIPT# 12968 RECORDED - DAKLAND COUNTY
1. Public Land Survey	T_5N_R	QT: T 1	G. WILL	IAM CADDELL, CLERK/REGISTER OF DE
abiio Earla Gurvey	TR	8E <u>J-1</u>		
	TR		_	
	<u> </u>	- SURVEY	St _	Compliance with
2. Property Controlling	S T R	RESUME STATE	ATION	ACT 345, P.A. 1990
in Section	S T R		APPROVEI	NON: 6-15-98 JS
3. Miscellaneous	S TR	MAR 2 1 20	M ⊝AKLAND	COUNTY REMONUMENTATION
Property in Sec.	S TR_) \$E	ER GROUP COMMITTEE
		# PDD (Ph. DOS 1 / Ch. D. 2	Regi	ster of Deeds Stamp & File Numbi
4.1.4345		SECTION		
5 Private Claims	ded Plat			
5. Private Claims			. 1 A B	CDEFGHIJKI
			2 - 6-	5
		-	3	
, Timothy J. Hart	in a field survey on	3-30 , 19 <u>98</u> do hereby state	that under 4 — 7 —	
				8-10-11-1
		of the current manual of survey instruc- igement or by a decree of a Court of		
The second bound like the leading	BIBLIES J. 4 AND 5 ANDVA WEI	'D IN CORTOYMOROO ISAND ALL WILL FAIL	B.47 - 1.4	17 16 15 14 1
recovered, found as expressed below	R Decree of a Court of f	aw; established, re-established, mo	numented, 7	╌╁╌╂╌╂╌╂╌╂╌╂╌╁╌╁╌┤
1000 teled, round as expressed bei	ow: ,		B19	20 21 22 23 2
NOTE: Not more than 2 come	ers, all in the same town a	nd range, may be recorded	9	
on this certificate.		and	10-30-	29 29 27 06 34
	•			29 28 27 26 25
		,	11	
			12 31-	$-\frac{32}{32}$ $-\frac{33}{34}$ $-\frac{34}{35}$ $-\frac{36}{36}$
A. Description of original mon	llment and secondaries	and an art are a	13	
Corner was not se	t in the 1823 G.	L.O. survey.		William Control of the Control of th
LCRC, L 7440, P 0	2			STATE OF MICH
1979, Pangus, fd	l" pipe			36 THEORY W. V.
S 20°E 9.86' 12'	" Oak			JHART TE
\$ 45°W 25.78' 15'	" Oak			* PROFESSIONAL
South 33.56 28	" Oak			SURVEYOR TE
				2 L
				7 No. 33136 WE
B. Description of corner evide	ence found and/or metho	d applied in restoring or reestable	ishina corner:	THE LAND SEE
				Millian
A fence/tree line	on pipe / it sou	th of the edge of a]	arge stream ru	unning agat and seet
corner J-13 in Ger	runs south from	the corner. Recover	ed a l''iron p	oipe East 56.36 ft at
Witnesses Recovere	desee county.	•		
S 70°E 34.20' Na	11/tag 12" Cham	a		
*S 20°E 9.86' Na	111/tag 12 Gier.	Ly		lo
*South 33.56' Na	11/tag 12 Oak		•	1
*S 45°W 25.78' Na	11/tag 16" Oak			K
	, , , , ,			
*Confirms LCRC				
C. Description of monument for	r corner and accessories	established to perpetuate legati	no tha marking at the	
Set concrete monum	ent with O.C. Ra	emon. brass cap 0.26	ing the position of the (corner:
recovered 1" iron	pine on the Town	smon. Blass cap 0.20	north of the	position of the
N 40°W 31.58° PK/	ramon tag F QU /	ah	Chah. D1 0	- 14
N 20°E 21.39' PK/	remon tag E 8" ()ak	State Plane C	
N 20°E 21.39' PK/remon tag E 8" Oak S 10°E 9.60' PK/remon tag W 20" Oak E 13360166.9059				
S 80°W 35.25' PK/	remon tag N 16"	0ak	n 10000100.30	J 7
				•
sional survivors -	TOD is accepted	by the Contractor and	d is generally	accepted by profes-
STORET SULVEYORS &	s the dest avail	able evidence of the	nosition of +1	ha artainal assess
Act 345 of P.A. 19	so accepted by t	he Oakland County Pe	er Group as es	tablished under
	T' C 89-1			
Signed by Committee	y >). If	Dat Dat	e <u>5-20-</u>	78
Surveyor's Michigan License No.	/ (33136			