

Act 345 of P.A. 1990.

Surveyor's Michigan License No.

33136

URFR 19758 PC 515

LAND CORNER RECORDATION CERTIFICATE 106329 Filing Requirement of Act 74, Mich. P.A. 1970 19758 PAGE For corners in \$7.00 MISC RECORDING Oakland Located in: Corner Code # \$2.00 REMONUMENTATION 03/30/1999 01:03:22 P.M. RECEIPT# 12968 PAID RECORDED - DAKLAND COUNTY 6. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS 1. Public Land Survey T <u>5N</u> R <u>8E</u> S YEVELL R Compliance with ACT 345, P.A. 1990 Т R 2. Property Controlling Т _ R APPROVED ON: 1-10-94 JS _ T in Section OAKLAND COUNTY REMONUMENTATION 3. Miscellaneous PEER GROUP COMMITTEE Register of Deeds Stamp & File Number Property in Section _ R_ SECTION _, Recorded Plat_ 5. Private Claims Timothy J. Hart , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Post set in 1823 G.L.O. survey; 5" W. Oak N 47°E 33 1ks; 4" W. Oak S 52°E 45 1ks. A) Unrecorded survey, Feldhauser, 1970, no corner witnesses (verified to Pipe "C") A) Unrecorded survey, Feldmauser, 1970, no collect without the ball of the bal STATE OF D) Unrecorded survey, Pangus, 1979, fd iron #19836 (2) E) Unrecorded survey, Carlson, 1986, fd iron #19836 (2) D) Unrecorded survey, Carlson, 1986, fd iron #1900. E) Unrecorded survey, Carlson, 1978, fd square head bolt (rejected) G) Unrecorded survey, Wiztnajtys, 1984, set 1/2" rerod & cap 21585 (rejected) (n) number of wintesses confirmed B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Recovered three separate survey iron monumenting the 1/4 corner position at the centerline intersection of Oak Hill and Bird Roads. Iron "A" is a No. 33136. 1/2" rerod recovered south of the centerline intersection. Iron "B" is PROFESSIONAL and Pipe "C" is a 3/4" pipe located at the approximate centerline intersection. The positions of Irons "A" & "B" were rejected as monumenting the corner due to lack of supporting evidence. The position of Pipe "C" (3/4" pipe) was accepted. Witnesses Recovered to Pipe "C" N 35°W 50.06' Nail/tag S 6" Oak(C) N 35°E 42.72' Nail W 48" Locust S 42°E 72.76' Nail/tag NE U. pole (C) S 40°W 42.35' Face st. sign (B,C) N 40°E 32.00' Nail W. 38" Locust (D,E) S 50°W 68.50' PK E 10" Spruce N 60°E 55.41' Nail/tag S 30° Maple (C) S 45°E 46.93' Nail NW fence post (B,D,E) (1) LCRC or survey confirmed C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod with 0.C. remonumentation brass cap, replacing 3/4" pipe. 49.97' PK nail/remon tag S. 6" Oak 55.33' PK/nail/remon tag S. 30" Maple N 35°W State Plane Coordinates N 60°E N473625.5816 S 42°E 72.70' PK nail/remon tag E. util pole E13364059.8774 S 50°E 68.49' PK nail/remon tag E. 10" Spruce The selected location is accepted by the Contractor and is generally accepted by profes-

sional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under

Date 3-8-99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975