UBBR 19758PG 518



LAND CORNER RECORDATION CERTIFICATE 106332 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in 19758 PAGE \$7.00 MISC RECORDING \$2.00 REMONUMENTATION 03/30/1999 01:03:22 P.M. RECEIPT# 12968 PAID RECORDED - OAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS 0akland Located In: Corner Code # (County) 1. Public Land Survey 5N R 8E Compliance with ACT 345, P.A. 1990 MOTATION 2. Property Controlling R 6-15-98 55 in Section APPROVED ON: R OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE 3. Miscellaneous WAR 21 2000 Property in Sec. Register of Deeds Stamp & File Numbe SECTION 4. Lot No. , Recorded Plat 5. Private Claims <u>Hart</u>, in a field survey on 3-26 , $19\underline{98}$ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration: Post set in 1823 G.L.O. survey; 13" W. Oak S 64½°E 6 lks; 7" Jack pine N 67½°W SENTHALL AND LODGE T 6002 D 512 Albright 1972 fd pinch top pine (2) STATE OF MICH A) LCRC, L 6002, P 512, Albright, 1972, fd pinch top pipe (2) B) LCRC, L 6153, P 167, Stonerock, 1973, fd pinch top pipe (1) C) LCRC, L 6748, P 607, Stonerock, 1973, fd pinch top pipe (1)

D) LCRC, L 6965, P 133, Pangus, 1977, fd 1/2" iron in mon box (2)

E) LCRC, L 10836, P 724, Brown, 1989, fd 1/2" iron in mon box (2)

F) LCRC, L 16117, P 009, Hart, 1996, fd iron in monument box (3)

(n) Indicates number of witnesses confirmed

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered 1/2" iron in monument box on the south edge of the asphalt road surface of Groveland Road, 14' south of centerline. TIMOTHY **PROFESSIONAL** Description of corner evidence found and/or method applied in restoring or reestablishing corner: Groveland Road, 14' south of centerline. Witnesses Recovered N 60°W 147.62 Nail/tag NW DE pole (F) N 30°W 58.73' Nail/tag W 10" Elm North 67.75' & 67.58' Nail/tag E DE pole (A-F) N 60°E 111.02' Nail/tag S 18" Oak (A&E) S 80°E 91.35' Nail/tag N 22" Oak (C,D&E) S 45°E 55.06' PK nail N 18" Oak (A&B) South 44.12' NE corner 2'x2' conc pillar (F) S 80°W 26.49' Centerline S leg County Rd sign (C) (L) indicates LCRC confirmed C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod w/0.C. Remon. cap in existing section box. N 60°W 147.62' PK/remon tag S util. pole North 67.75' PK/remon tag E util. pole State Plane Coordinates N 60°E 111.02' PK/remon tag S 18" Oak N 497382.3147 S 45°E 55.08' PK/remon tag N 18" Oak E 13365697.6530 The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990. Signed by Brock Surveyor's Michigan License No