

Ju 1495 | 25242

UBIR 15517ec410

Filing Requirement of Act 74, Mich. P.A. 1970 \$ 7.00 NISCELLANEOUS RECORDING

LAND CORNER RECORDATION CERTIFICATE

Oakland (County)	_ Located In:Oxford Twp. Corner	Code #	14 JUL 95 8:38 A.M. RECEIFT# 9B	
			PAID RECORDED - JAKLAND COUNT	
1. Public Land Survey	т <u>5N R 10В</u>	12	LYNN D. ALLEN, CLERK/REGISTER OF DEED	,
	T R	· ·		
			Compliance with ACT 345, P.A. 1990	
2. Property Controlling			APPROVED ON: 6-14-95 Toms	
in Section		·····	OAKLAND COUNTY REMONUMENTATION	
3. Miscellaneous	ST_R		- PPA GROUP COMMITTER	
Property in Section	S T R		Register of Deeds Stamp & File Number	_
4. Lot No	orded Plat			
				ተ
			2 - 6 5 3 3 3 3	1-
			3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	T
. Huston K. Kennedy in	a field survey onApril 26	i 10 9 5	4-7-8-9-10-11	12-
do hereby certify that under requir	rements of P.A. 74, Michigan P.A. of 1970, the c	omer points mentioned	6 18 17 16 15 14	13-
	formance with regulations and rules therefore as of the United States Department of the Int		7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	Ĭ
Management or by a decree of a	Court of Law and/or that the corner points men	tioned in lines 3, 4 and	8 19 20 21 22 23	 24-
	th the rules of the Michigan Board of Professi shed, re-established, monumented, re-monume		9	╀
as expressed below:	Sieg, ie establisieu, monumenteu, fermonume	inted, recovered, round	10 30 29 28 27 26	25-
	ers, all in the same town and range, may be	e recorded	11 + + + + + + + + + + + + + + + + + +	十
on this certificate.	·		12 31 32 33 34 35	36− [
A. Description of original mo	onument and accessories and/or subsequ	uent restoration:	131	٠.,
1.) 1973-Lester, PS #18998 2.) 1994-Kennedy, PS #1762	t Post 15" Black Oak N36°E 102 Links; LCRC L.6028, Pg.641 - Fnd 1/2" Pipe 3; LCRC L. 14419, Pg.398- Fnd 1/2" Iron 3; Unrecorded Survey - Fnd 1/2" Iron Ro	Rod d, used same wit as 1	994 LCRC	
		•		
•				
B. Description of corner evid	dence found and/or method applied in re	storing or reestablishi	ng comer:	
1995 Kennedy Surveying, Inc East & West.	c Kennedy, PS #17623 - Fnd 1/2" Iron Ro	xd 12" below surface. I	A tree-fence row extending to the North, S	out
Witnesses from LCRC	1 & 2 were used to recover and verify t	he location of the fo	und 1/2" Iron Rod.	
I accepted the found	1/2" Iron Rod as the best evidence of t	he original corner po	sition.	
			7.60	\checkmark
FIELD MEASUREMENTS BE	94.[839]		11.06	. •
T-12 +0 T-11 2407 47	Ft., GLO = 40 chains or 2640.00 Pt.		7	
1-12 to 1-11 2401.47	rt., div - 40 chains of 2040.00 rt.			
C. Description of monument	t for comer and accessories established	to perpetuate locating	the position of the comer:	
I-12 I replaced the found cap stamped Oakland O	1/2" Iron Rod with a 1/2" Iron Rod encas	ed in a 4" diameter c	oncrete cylinder 36" long w/2" diameter b	ras
NO2'W 33.19' Set PK &	Remon. Washer East face 13" Oak	•	HUSTON	
	Remon. Washer North face 20" Oak PK & Remon. Washer Bast face 27" Oak		WHILE OF MICHAEL	
	Remon. Washer North face 12" Oak		Mark All Market	Ł
			HUSTON	,
The selected location is a position of the original of	accepted by me and is generally accepted	1 by Professional Sur	veyors as the perchangual and a national contract of the contr	ÇU T
horseion of the original o	A 4 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		SURVEYOR SURVEYOR	~ j
	/		17623	Š
Signed by	<u> </u>	Date J	Tune 14, 1995 PROFFSSIONAL SURVEY	•
Surveyor's Michigan License	No. 17623		MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 20, 1971	
Surveyor's Michigan License	110		REVISED MAY 14, 1975	1