STATE OF HICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 3 DEC 1999 2:07:47 PM For corners in JOSEPH E. HERTEN Corner Code# Located In: REGISTER OF DEEDS Oceana 100933 G - 12T 13NR 15W 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat 5. Private Claims 3 Randolph Hepworthin a field survey on August 12, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 7 8 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 on this certificate. 11 13 A. Description of original monument and accessories and/or subsequent restoration: **GREENWOOD TOWNSHIP** G-12 1/4 CORNER COMMON TO SECTIONS 33 & 34 T13N, R15W GLO J. Mullett 1838 SET POST 10" Maple N88°E (171ks) 11.2' 10" Maple Book A, Pg. 124, S Edson, 1881; "Sand Stone with a notch on top." Book A, Pg. 156, S Edson, 1881; "Sand Stone with a notch on top." Oceana County Remonumentation Peer Group Reviewed & Approved OCRC WITNESS BOOK Undated Large Stone 30" (word is missing) West 31.4' 10" Silver Maple \$35°W 58.0' 30" Tr. Elm \$60°E 47.6' 10-27-99 J. Randorph Hepworth Unrecorded Survey, JR Hepworth #26457, 10/27/95 Fd 1/2" Iron / cap # 18987 Fd 16d Spk in N Face 14" Maple 96°Az 40.61' 16d Spk in SE Face P.Pole 45° Az 90.93' Oceana County Surveyor 16d Spk in SE Face P.Pole 204°Az 66.88' 16d Spk in E Face 24" Maple 270°Az 67.78' 50" Oak 16d Spk in N Face Recorded Survey Jkt # 593, Carl Englert, Jr., # 18987, 8/21/96, Set Iron Bar (7/12/95) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. I found a 1/2" iron and cap (#18987) in the centerline of N-S Road. Occupation lines run to the east and to the west. All OCRC witnesses are gone. No documentation is known to me as the method of how Englert set this corner other than the local collateral evidence as to the position of the original corner. I accept the Iron as the best available evidence of the position of the origit. I corner. No evidence is known to me that would lead me to believe the corner should be at another location. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" above the 1/2" Iron which was driven down. 42°az of MICHIG Power Pole SE Face 60d spk 45.72 **EDM** 227°az 30" Maple N Face 60d spk 29.58 EDM 283°az 12" Ash N Face 60d spk 230.93" EDM 160°az Power Pole J. RANDOLPH **NE Face** 66.88 ∍60d spk

24" Maple

26457

F Face

Eurveyor's Michigan License No.

#60d spk

aigned by

TO FREDRY FORM APPROVED BY MICHIGAN STATE BOARD OF PROPESSIONAL ST

Date November

30

RVENORS, JAN. 28, 1971

HEPWORTH

LAND

SURVEYOR

NO.

26457