MAY 1 6 1997

LAND CORNER RECORDATION CERTIFICATE

10071.0

STATE OF MICHIGAM COUNTY OF COLLAR

For corners in	Filing Requireme	ent of Act 74, Mich. P.A. 1	970 90 UEU 19 AH 113
Oceana (County)	Located In:	Corner Code #	and the state
Public Land Survey	T 13NR 16W	C-4	Grand REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Section 	T R T R S T R S T R S T R S T R		Register of Deeds Stamp & File Number
	Recorded Plat		ABCDEFGHIJKI
5. Private Claims			2 6 - 5 - 4 - 3 - 2 3
, J. Randolph Hepwort	바, in a field survey on	May 16 , 19 96 ,	4 7 8 9 10 11 11 15

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1/4 Corner Common to Sections 7 & 8 T13N, R16W Otto Township

SET POST 14" Beech \$70°W 181

LCRC # 100198 J. Clapp # 14091 10/13/76 Fd Steel Bar 8" Pine ESE 43.07"

Unrecorded Survey R Hepworth # 25457 12/29/88 Fd T Iron, Cen N-S Rd

12" R. Pine 111°AZ 43.15' 10" Tw R. Pine 130°AZ 50.25' 4" Cherry 320°AZ 52.8'

8" Tw Pine SE 50.36"

14" Tr Beech 253*AZ 111.42'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found both Clapp, 1976, and all of the JRH, 1988 witnesses. This road was reconstructed in 1989-1990 and JRH witnessed the corner prior to construction. I found that this corner stake is in about 4' of new fill and found an empty monument box 0.35' SW of the Intersection of JRH witness distances. I removed the monument box and set a 4"x20" Harrison cast iron Monument at the 1988 witnessed position.

This monument was accepted as the best evidence of the corner and was accepted as being a careful and faithful perpetuation of the original corner. No evidence is known to me that would lead me to believe that the corner should be in another location. I placed a 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" & "26457" the 1988 position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

C-3 to C-4			2653.48	EDM
center	6" Cherry	298°az	52.7	EDM
60d spk W Face	18" tw Oak	156°az	126.92	EDM
60d spk SE Face	14" tr Beech	250°az	111.37	EDM
60d spk NE Face	10" tw R Pine	127°az	50.17	EDM
60d spk N Face	12" R Pine	108°az	43.09	EDM
4"x20" Harrison Cast I	ron Monument, stamped	"County Surveyor"	& "26457"	
U-4 1/4 Comer (Johnnon to Sections / &	8 113N, R16W	Otto Township)

Oceana County Remonumentation Peer Group Reviewed & Approved

J. Randolph Hepworth

of Michig J. RANDOLPH HEPWORTH LAND SURVEYOR MANUFACO LAND

Oceana County Surveyor

Surveyor's Michigan License No.

December 5, 1996

Date

26457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN 28 1971