FEB 2 1 %

COMM

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF CCEARA RECEIVED FOR

JUL 10 P2:48

Oceana County	Located In:	Corner Code ##	· # #	f E	•	
1. Public Land Survey	T 13 R 18 T R T R T R	G-11		REGISTER OF		,
in Section 3. Miscellaneous	S T R S T R S T R S T R			Register of Deeds Stamp & File Number		
4. Lot No, Rec 5. Private Claims			A B C D	EFG	ні	JKLN
5. Flivate Claims			2 6 5 5 4 7 7 8		3	
I.J. Ramblish Hegwith , it do hereby certify that under required in lines 1 and 2 above were in courrent manual of survey instructing Management or by a decree of a Chabove were in conformance with the Court of Law; established, reserversed below:	rements of P.A. 74, Michigan P.A. onformance with regulations an ions of the United States Depart ourt of Law and/or that the corne he rules of the Michigan Board o	of 1970, the corner points mention of rules therefore as required in Iment of the Interior, Bureau of Les points mentioned in lines 3, 4 and Land Surveyors or by a Decree	ned 6 18 17- the and 7 19 20- of a 19 20-		15 22 27	2324

Description of original monument and accessories and/or subsequent restoration:

G-11 Corner Common to Sections 27, 28, 33, and 34 T13N, R18W

CLAYBANKS TOWNSHIP

12" Sugar S80°E 9.2"

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Book A, Pg 146; S. Edson, 1882; Corner not described or witnessed.

Book A, Pg 148; S. Edson, 1882; A pyrmidical, reddish stone about 21" long set with apex up

OCRC WITNESS: Undated, pre-1950; 1" Round iron

12" Maple South 22.4

on this certificate.

GLO SET POST

14" Maple S45°E 36.0'

18" Beech N24 1/2°W 13.9"

Unrecorded survey; Hepworth, PS26457, 8-13-86; Found 1/2" Iron

30" Maple 135°az 36.44

16" Maple 186°az 22.86

P Pole 24°az 65.44

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

I found a 1/2" Iron 2" below the surface in the center of an east-west & north gravel road. A faint occupation line (field division) runs to the south. Upon excaviation and removal of the 1/2" Iron, I found it to be a riser for a 1" round Iron which is beside a greenish-redish stone at 18" below the surface. On further excavation, the stone appeared to be pyrmidical with point up and at least 18" long.

Both OCRC witnesses are standing and measure consistent. The stone is as described by Edson, 1882.

Further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the position of the corner. The Found 1/2" Iron is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Corner Common to Sections 27, 28, 33, and 34 T13N, R18W CLAYBANKS TOWNSHIP Set "COUNTY SURVEYOR" HARRISON 4"X20" cast iron Monument above the found 1/2" Iron which was driven down and above the 1" round from and beside the large redish stone

60d spk SW Face	30" Maple	127°az	36.50	EDM
60d spk W Face	18" Maple	179°az	22.86	EDM
PK Nail NW Face	Power Pole	23°az	65.46	EDM
60d spk N Face	30" Maple	260°az	164.85	EDM
60d spk S Face	20" Ash	98°az	98.67	EDM
found 1/2" Iron/cap LS264	457	176°az	33.02	EDM

Oceana County Remonumentation Peer Group Reviewed & Approved

5-25-95

TRU J. Randolph Hepworth

Oceana County Surve

"Surveyor's Michigan License No.

=Signed by

RANDOLPH HEPWORTH LAND SURVEYOR NO.

HO OF LAND SORVEYORS, JAN. 28, 1971 No take the Prised MAY 14, 1975