FES 2 2 1995

Surveyor's Michigan License No. 26457

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF CCEANA RECEIVED FOR REGISTA

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

100662 95 DEC 15 P3:02

1. Public Land Survey	For corners in Oceana	Located In:	moquii omoni	Corner Code #				. J. U.,
1. Public Land Survey  T R  T R  T R  T R  T R  T R  T R  T		Located III.		COMPONE COGO III		Jen-jer	بدر میدر م وسوع	Parte Sec
1. Public Land Survey  T R  T R  T R  T R  T R  T R  T R  T		1 4 N	. 15W	₩_O		REC	ister of D	EEUS
T R R R R R R R R R R R R R R R R R R R	<ol> <li>Public Land Survey</li> </ol>	1 741	R		·	•		, <b></b>
2. Property Controlling S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number R R Register of Deeds Stamp & File Number R R R R R R R R R R R R R R R R R R R								
in Section S T R Property in Section S T R Private Claims  J. Randolph Helpworth Survey on Nov. 20, 1995 Obtained by settly that under requirements of Pa-74, Michigan Pa-A of 1970, the corner points mentioned himself of the Common of the Common of Section S of the United States Department of the Interior, Bureau of Land Management or by a discrete of a Count of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above where in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above where in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above where in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above where in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above the rule of the Michigan Board of Professional Surveyors or by a 5 above the Rule of the Michigan Board of Professional Surveyors or by a 4 above rule of the Michigan Board of Professional Surveyors or by a 4 above rule of the Michigan Board of Professional Surveyors or by a 4 above rule of the Rule of the Michigan Board of Professional Surveyors or by a 4 above rule of the Rule o		T	R					
3. Microellaneous S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Section S T R Register of Deeds Stamp & File Number Property in Section S Register of Deeds Stamp & File Number Property in Section S Register of Deeds Stamp & File Number Property in Section S Register of Deeds Stamp & File Number S Register of Deeds Register of Deed	2. Property Controlling				-			•
Property in Section S T R Recorded Plat  5. Private Claims  J. Randolph Helpworth 5. Private Claims  J. Randolph Helpworth 6. Recorded Plat 6. Private Claims  Nov. 20, 1095 6. Application of conformance with regulations and rules therefore as required in these 1 and 2 above were in conformance with regulations and rules therefore as required in the sound of the property intercolors of control of the world of but the corner points mentioned in lines 3, and 3 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a 5 above were in conformance, and in the same town and rune, may be recorded on this confidence on the same town and rune, may be recorded on this confidence on the same town and rune, and the rule of the same town and rune, may be recorded on this confidence on the same town and rune, and the rule of the same town and rune, and the rule of the Michigan Board of Professional Surveyors or by a 4 above the same town and rune, and the rule of the Same town and rune, and the same town and		ST	R		-			
4. Lot No	• • • • • • • • • • • • • • • • • • • •				Regis	ster of Deeds S	3tamp & Fi	ile Number
5. Private Claims  J. Randolph Ilepworth at under requirements of PA. 74, Michigan PA. of 1970, the corresponts mentioned interest and 2 above were in correct mentioned interests and 2 above were in the suited Suzer. Department of the letteric, Bursus of Land Management or by a decree of a Court of Law and/or that the corresponts mentioned in these 3, 4 and 5 above were in correct mentioned in the suited Suzer. Department of the letteric, Bursus of Land Management or by a decree of a Court of Law and/or that the corresponts mentioned in these 3, 4 and 5 above were in conformance with he rules of the Michigan Beard of the Professional Suzery or by a Decree of a Court of Law and/or that the corresponts mentioned in these 3, 4 and 5 above were in conformance with he rules of the Michigan Beard of Professional Suzery or by a Decree of a Court of Law established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12 Marje N70°E 9.9° 8° Henribox S51°E 5.3°  Blook N, Pg 8° F. Welfaror, 1990; O'ld quater post established with charcoal, broken bricks, crockery, etc. 12 Marje N70°E 9.9° 10°C dignater post.  Book N, Pg 8° F. Welfaror, 1990; O'ld quater post est by Hawley.*  N obe Pg 22439 Urresponded Survey My 179°S 64 12°P lope by projection and measurement west from a found Wagon Hub & crockery at the 5 1/16 Cor and SE Corner of Section 21. Measurement = 1313.38°. No Witnesses given to mo.  LCRC #100483 R Heyworth PS24857 124-482 Found 1/2°P lope by projection and measurement west from a found Wagon Hub & crockery at the 5 1/16 Cor and SE Corner of St.54e° 10°C celar NE 16.19° 10°W Pine N N 37.40° 16° Healen St.54e° 10°C celar NE 16.19° 10°W Pine N N 37.40° 16° Healen St.54e° 10°C celar NE 16.19° 10°W Pine N N 37.40° 16° Healen					<u> </u>			
do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corresponds mentioned in lines 1 and 2 above were in conformance with States. Department of the Intention, Bureau of Land Management of the Management of	4. Lot No,	Recorded Plat				A B C D	E F G	HIJK
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current income in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current income of a Court of Law and/or that the corner points mentioned in lines 3, the property of the 2 above were in conformance with the rules of the Michigan Board of Processing of the 3 above were in conformance with the rules of the Michigan Board of Processing of the 3 above were in conformance with the rules of the Michigan Board of Processing of the 3 above were in conformance with the rules of the Michigan Board of Processing of the 3 above were in conformance with the rules of the secretary of	5. Private Claims					2 6	<del></del>	
do hereby certify that under requirements of PA. 74, Michigan PA. of 1970, the corner points intended in lines 1 and 2 does were in conformance with regulations and rives therefore as required in the current manual of survey instructions of the United States Department of the medical manual of survey instructions of the United States Department of the medical manual of survey and the current manual of survey and control country of the Michigan Board of Perfessional Surveyors or by a boxen of a Country of Lart, restablished, re-established, monumented, re-monumented, recovered, found as entressed below.  NOTE: Not more than 4 comers, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration: F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12 Maple N70°E 9.9 8 Hemicok S51°E 5.3  Book A, Pg 578, H.C. Hawley, 1883, "Hole 3' deep, 3 1/4" dia, filled with charcoal, proven bricks, crockery, etc. 127 Maple N70°E 9.9 10 Hemicok N35°W 119.9  Book C, Pg 2; F. Welmore, 1900. Old quanter post at by hawley.*  N. Ochs Pe 22439 Unrecorded Survey May 1576 Set 127" Pipe by projection and measurement west from a found Wegen Hub & crockery at the E 1/18 Cor and SE Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the center of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement of the mount of the center of an old easievest rose beat at the edge of waverray area. On excavation and removal of the pipe. 1 did not for the center of an old easievest rose beat at the edge of waverray area. On excavation and removal of the pipe. 1 did not fill area of the road bed in the swarp. No occupatio				•		3	<del></del>	+
do hereby certify that under requirements of PA. 74, Michigan PA. of 1970, the corner points intended in lines 1 and 2 does were in conformance with regulations and rives therefore as required in the current manual of survey instructions of the United States Department of the medical manual of survey instructions of the United States Department of the medical manual of survey and the current manual of survey and control country of the Michigan Board of Perfessional Surveyors or by a boxen of a Country of Lart, restablished, re-established, monumented, re-monumented, recovered, found as entressed below.  NOTE: Not more than 4 comers, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration: F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12 Maple N70°E 9.9 8 Hemicok S51°E 5.3  Book A, Pg 578, H.C. Hawley, 1883, "Hole 3' deep, 3 1/4" dia, filled with charcoal, proven bricks, crockery, etc. 127 Maple N70°E 9.9 10 Hemicok N35°W 119.9  Book C, Pg 2; F. Welmore, 1900. Old quanter post at by hawley.*  N. Ochs Pe 22439 Unrecorded Survey May 1576 Set 127" Pipe by projection and measurement west from a found Wegen Hub & crockery at the E 1/18 Cor and SE Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the center of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement = 1313.98. No Winesses given to mount of the Corner of Section 21. Measurement of the mount of the center of an old easievest rose beat at the edge of waverray area. On excavation and removal of the pipe. 1 did not for the center of an old easievest rose beat at the edge of waverray area. On excavation and removal of the pipe. 1 did not fill area of the road bed in the swarp. No occupatio			3.7.	20 100	E	4	+	10-1-11-
In inset a fard 2 above were in conformance with regulations and rules therefore as regulated in the current manual of survey instructions of the United States Department of the Interior, Burasu of Land Management or by a decree of a Court of Law and/or that the center points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Dorme of a Court of Law, established, re-established, morumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 comers, all in the same town and range, may be recorded on the conflicate.  A Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12 Maple N70°E 9.9° 8° Hembox 85°1°E 5.3° Book P. 975 H. CH. Bewley, 1883 "Nios 4 Sep. 3.14" Gail, fillow with charcoal, broken bricks, crockery, etc. 12" Maple N70°E 9.9° 10" Hembox N35°W 11.9° Book B. 98 5; F. Weltmore, 1900. 101 quarter post. Book B. 98 5; F. Weltmore, 1900. 101 quarter post. Book B. 98 5; F. Weltmore, 1900. "Old quarter post upon the fillow of the comer of Section 21. Measurement = 131.998". No Winesses given to me.  LCRC \$100483 R Hepworth PS26457 12-4-92 Found 1/2" Pipe, Grader blade bestde-guard stake Tv of 6" Maple S 15-46" 10" Cegar NE 16.19" 10" W Pine N 97.40" 10" Hembox SE 43.22" 10" W Pine N 40.12"  B. Description of comer evidence found and/or method applied in restoring or reestablishing corner 1 found a 1/2" Pipe projecting 6" above the ground 8" SW of a grader bade projecting 3 feet. Pipe is 5 feet north of the center of an old eastwest road bad the degle of swampy are. On excavation and removal of the pipe. I clin child any evidence of blick, crockery or charcoal. Comer falls in 2 foot ± fill area of the read bed in the swamp. No occupation is visible to the north; a single-strand wire tree-to-tree runs to the south from this comer.  Further search of the area failed to yield any other evidence for a conf	J. Randolph He	pworth, in a field survey on	INC	20, 199		5	+++	++++
Management of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in line 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Description of Court of Law nestbalished, re-established, re-monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12" Maple N70°E 9.9" 8" Hemlock S51°E 5.3"  Book A, Pg 578, H.C. Hawley, 1883, "Hole 3" deep, 3 114" dia. filled with charcoal, proken bricks, crockery, etc.  12 Maple N70°E 9.9" 10" Hemlock NS5°W 11.9"  Book C, Pg 2; F. Wetnore, 1900. Of quarter post.  Book B, Pg 578, H.C. Hawley, 1893, "Hole 3" deep, 3 114" dia. filled with charcoal, proken bricks, crockery, etc.  12 Maple N70°E 9.9" 10" Hemlock NS5°W 11.9"  Book B, Pg 5; F. Wetnore, 1900. Of quarter post and the control of the control	in lines 1 and 2 above were in	n conformance with regula	tions and rules the	erefore as required in	the current	6 18 17-	16-1-	1514
5 above were in conformance with the rules of the Michigen Board of Professional Surveyors or by a Deceme of a Count of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12" Maple N70"E 9.9" 10" Hernlock N55"W 11.9"  Book A, Pg 578, H.C. Hawley, 1983, *Hole 3" deep, 3 1/4" dia. filled with charcoal, broken bricks, crockery, etc. 12" Maple N70"E 9.9" 10" Hernlock N55"W 11.9"  Book B, Pg 5; F, Wetnions, 1900. "Old quarter post.  Book B, Pg 5; F, Wetnions, 1900. "Old quarter post.  Book B, Pg 2439 Unrecorded Survey, May 1976 Set 12" Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 1313.98". No Witnesses given to me.  LCRC #100483 R Hepworth P828467 124-92 Found 1/2" Pipe, Grader blade testide-guard stake  Twe "6" Maple S 15.46" 10" Cedar NE 16.19" 10" W Pine NW 37.40" 16" Hernlock SE 43.22'  B.Description of corner evidence found and/or method applied in restoring or restablishing corner  I found a 1/2" Pipe projecting 5" above the ground 8" SW of a grader blade projecting 3 feet. Pipe is 5 feet north of the center of an old east-west tread bed at the edge of swampy area. On excavation and removal of the pipe, 1 cld not find any evidence of brick, crockery or charcoal. Corner falls in 2 tool ± fill area of the road bed in the swamp. No occupation is visible to the north, a single-strand wite fuer-time time to the south from his corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Feet 144 CORNER COMMON TO SECTIONS 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP Set "County Surveyor Harrison 4"X20" Cast Iron Monument in place of the found 1/2" Pipe is december of the	manual of survey instruction	ons of the United State	s Department of	the Interior, Burea	u of Land	8 1920-	21-	-2223
as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12 Maple N70°E 9.9° 8" Hemlock S51°E 5.3' Book A, P9, 678, H.C. Hawley, 1883, "Hole 3' deep, 3 14" dia, filled with charcoal, broken bricks, crockery, etc. 12 Maple N70°E 9.9° 10" Hemlock N35°W 11.9' Book C, P9.2° F. Wetmore, 1900. 'Old quarter post set by Hawley."  N. Ochs Ps 22439 Unrecorded Survey May 1976 Set 1/2" Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cort and SE Corner of Section 21. Measurement = 1313.98'. No Witnesses given to me.  LCRC #100453 R Hepworth PS26457 12.4-92 Found 1/2" Pipe, Grader blade beside-guard stake  Tw 9"6" Maple S 15.46" '10" Cedar NE 16.19' 16" W Pine NW 37.40' 18" Hemlock SE 43.22' 10" W. Pine N 40.12'  B.Description of corner evidence found and/or method applied in restoring or reestablishing corner  I found a 1/2" Pipe projecting 6" above the ground 8" SW of a grader blade projecting 3 feet. Pipe is 5 feet north of the center of an old eastweet roac bed at the edge of swarney area. On excavation and renoval of the pipe, I did not find any sudence of brick, crockery or charcoal. Corner falls in 2 foot at fill area of the road bed in the swarney. No occupation is visible to the north; a single-strand wire tree-d-tale must to the south from his corner.  Futher search of the area falled to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the position of the corner and accessories established to perpetuate locating the position of the corner.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  Puter Good Statement approved Date:  12 - 14 CORNER COMMON TO SECTIONS 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP Set 'County Suveyo	5 above were in conformant	ce with the rules of the M	1ichigan Board of	Professional Surveyo	ors or by a		<del>  •</del>	<del>                                      </del>
Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12" Mapie N70"E 9.9" 8" Hembox 55"E 5.3"  Book A, Pg 578, H.C. Hawley, 1883, "Hole 3' deep., 3 /4/" dis. filled with charcoal, broken bricks, crockery, etc.  12" Mapie N70"E 9.9" 10" Hembox N85"W 11.9"  Book C, Pg 2". F. Weimone, 1900. Oid quarter post set by Hawley."  N. Ochs Pa 22439. Unrecorded Survey May 1976 Set 12" Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 1313.98'. No Witnesses given to me.  LCRC #100483 R Hepworth P326457 124-49 E found 1/2" Pipe, Grader blade beside-guard stake  Tw 8"6" Mapie 3 15.48" 10" Cedar NE 16.19" 19" W Pine NW 37.40" 18" Hembox SE 43.22"  10" W, Pine N 40.12"  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner  I found a 1/2" Pipe projecting 6" above the ground 8" SW of a grader blade projecting 3 feet. Pipe is 6 feet north of the center of an oid eastweet road bed at the edge of swampy area. On excavation and removal of the pipe, I did not find any evidence of brick, crockery or charcoal. Comer falls in 2 foot s fill area of the road bed in the swamp. No occupation is visible to the north; a single-strand wire tree-to-tree runs to the south from this comer.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Fig 1/4 CORNER COMMON TO SECTIONS 21 AND 28 T14N, R16W NEWFIELD TOWNSHIP Set "County Surveyor" Harrison 4"X20" Cast Iron Monument in place of the found 1/2" Pipe 60d spk W Face  10" Pipe 60d spk W Face 10" Pipe 10" Approved  Date: 12" 7" 9" Set 10" Pipe 1		stablished, re-established,	monumented, re-	-monumented, recove	ered, found	10 30 29		-2726
on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  F-9 1/4 CORNER COMMON TO SEC. 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP  GLO SET POST 12* Maple N70*E 9.9 8* Hemicok S51*E 5.3* Book A, Pg 578, H.C. Hawley, 1893, "Hole 3* deep, 3 14** dia. filled with charcoal, broken bricks, crockery, etc. 12* Maple N70*E 9.9* 10* Hemicok N35*W 11.9* Book C, Pg 2: F. Wetmore, 1900. *Old quarter post set by Hawley.*  N. Ocha Ps 22439 Urrecorded Survey May 1976 Set 1/2* Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 131385. No Witnesses given to me.  LCRC #100483 R Hepworth PS28457 12-4-92 Found 1/2* Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 131385. No Witnesses given to me.  LCRC #100483 R Hepworth PS28457 12-4-92 Found 1/2* Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 131385. No Witnesses given to me.  LCRC #100483 R Hepworth PS28457 12-4-92 Found 1/2* Pipe By Drigetion of the corner of Section 21. Measurement = 131385. No Witnesses given to me.  LCRC #100483 R Hepworth PS28457 12-4-92 Found 1/2* Pipe Royal Pipe Section 21. Measurement = 131385. No Witnesses given to me.  LCRC #100483 R Hepworth PS28457 12-4-92 Found 1/2* Pipe No Witnesses given to me.  I found a 1/2* Pipe projecting 6* above the ground 8** SW of a grader bade projecting 3 feet. Pipe Is 5 feet north of the center of an old easievest road bed at the edge of savenay area. On excavation and removal of the pipe I, 16 and find any evidence of brick, crockery or charcoal. Corner falls in 2 foot a fill area of the road bed in the explanation and removal of the pipe I, 16 and find any evidence of brick, crockery or charcoal. Corner falls in 2 foot a fill area of the road bed in the explanation and removal of the pipe I, 16 the pipe I, 16 the pipe I,		corners all in the same	town and range	a. may be recorded		11		
GLO SET POST 12" Maple N70"E 9.9' 8" Hemlock S51"E 5.3' Book A, Pg 578, H.C. Hawley, 1883, "Hole 3" deep, 3.14" dia. filled with charcoal, broken bricks, crockery, etc. 12" Maple N70"E 9.9" 10" Hemlock N35"W 11.9' Book C, Pg 2; F. Wetmore, 1900; Old quarter post set by Hawley."  N. Ochs Ps 22439 Unrecorded Survey May 1976 Set 1/2" Pipe by projection and measurement west from a found Wagon Hub & crockery at the E 1/16 Cor and SE Corner of Section 21. Measurement = 1313.96'. No Witnesses given to me.  LCRC #100483 R Hepworth Ps26457 12-4-92 Found 1/2" Pipe, Grader blade beside-guard stake Tw 8" 6" Maple S 15.46" 10" Cedar NE 16.19" 16" W Pine NW 37.40" 18" Hemlock SE 43.22'  10" W. Pine N 40.12'  B.Description of corner evidence found and/or method applied in restoring or reestablishing corner  I found a 1/2" Pipe projecting 6" above the ground 8" SW of a grader blade projecting 3 feet. Pipe is 5 feet north of the center of an old eastwest road bed at the edge of swampy area. On excavation and removal of the pipe, I did not find any evidence of brick, crockery or charcoal. Corner falls in 2 foot ± fill area of the road bed in the swamp. No occupation is visible to the north, a single-strand wire tree-to-tree runs to the south from this corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yield any other evidence for a conflicting position for the corner.  Further search of the area failed to yiel				,,, 20		12 31 32	33-	-3435
F-9 1/4 CORNER COMMON TO SECTIONS 21 AND 28 T14N, R15W NEWFIELD TOWNSHIP Set "County Surveyor" Harrison 4"X20" Cast Iron Monument in place of the found 1/2" Pipe 60d spk W Face 10" Pine N10"E 40.12 EDM 60d spk W Face 12" Cedar N80"E 16.19 EDM 60d spk E Face 18" Hemlock S15"E 43.22 EDM 60d spk NE Face 16" W Pine N45°W 37.40 EDM 60d spk W Face 8",6" Maple S5"W 15.46 EDM  O orna County Street Approved  Date: 12 - 7 - 9 S  J. Rangolph Hepworth Oceana County Surveyor	GLO SET POST Book A, Pg 578, H.C 12" Maple Book C, Pg 2; F. We Book B, Pg 8; F. We N. Ochs Ps 22439 L at the E 1/16 Cor and LCRC #100483 R H. Tw 8" 6" M 10" W. Pin  B.Description of co I found a 1/2" Pipe pi west road bed at the Corner falls in 2 foot the south from this c  Further search of the evidence for the posi	12" Maple N70°E . Hawley, 1883, "Hole 3'd N70°E 9.9' 10" Hemloc etmore, 1900; Old qua etmore, 1900; "Old qua etmore, 1900; "Old qua do SE Corner of Section 21. epworth PS26457 12-4-5 laple S 15.46' 10" Ced e N 40.12' rner evidence found and rojecting 6" above the grouedge of swampy area. Ou ± fill area of the road bed orner.	E 9.9' 8" H eep, 3 1/4" dia. fil ck N35"W 11.9' inter post. inter post set by Ha 1976 Set 1/2" Pipe Measurement = 92 Found 1/2" Pi ar NE 16.19' 1  Mor method appli und 8" SW of a gra n excavation and r in the swamp. No	emlock \$51°E led with charcoal, broawley."  by projection and me 1313.98'. No Withe ipe, Grader blade bes 6" W Pine NW 37.40  ed in restoring or reader blade projecting are removal of the pipe, I to occupation is visible a conflicting position.	NEWFIELD To 5.3' bken bricks, crock easurement west esses given to me ide-guard stake 0' 18" Hemlock establishing cor 3 feet. Pipe is 5 did not find any e to the north; a sil	from a found Ware.  SE 43.22'  Ther  feet north of the covidence of brick, and the cov	center of an occockery or or cree-to-tree ru	old east- charcoal. uns to ilable
Set "County Surveyor" Harrison 4"X20" Cast Iron Monument in place of the found 1/2" Pipe 60d spk W Face 10" Pine N10°E 40.12 EDM 60d spk S Face 12" Cedar N80°E 16.19 EDM 60d spk E Face 18" Hemlock S15°E 43.22 EDM 60d spk NE Face 16" W Pine N45°W 37.40 EDM 60d spk W Face 8",6" Maple S5°W 15.46 EDM  O 2113 Cast Cast Cast Cast Cast Cast Cast Cast	C. Description of m	onument for corner and	accessories esta	ablished to perpetua	te locating the p	osition of the co	rner.	
60d spk  E Face	Set "County Surveyo 60d spk W Face	or" Harrison 4"X20" Cast Ir 10" Pine	on Monument in p N1ฏ°E	lace of the found 1/2" 40.12	Pipe EDM		Secretary.	1)14
60d spk NE Face 16" W Pine 8",6" Maple S5°W 15.46 EDM  O oma Co six Someomory den Peer Group Reviewed & Approved  Date: 12-7-95  J. Rangolph Hepworth Oceana County Surveyor	•						(1/ 1311) X	
O comp Co ota De monaci den Peer Group Reviewed a Approved  Date: 12-7-95  J. Rangolph Hepworth Oceana County Surveyor	60d spk NE Face	16" W Pine	N45°W				HANDOLPH.	
Peer Group Reviewed & Approved  Date: 12-7-95  J. Rangolph Hepworth Oceana County Surveyor	oou sph vv race				COIN	2 * 1		1 2 %
Date: 12-7-95  J. Rangolph Hepworth Oceana County Surveyor								
J. Rangolph Hepworth Oceana County Surveyor				• •			RO.	
Oceana County Surveyor		Da	121				200337 Successor	
$D_{1}$ , $D_{2}$ , $D_{3}$						All Co		
0//11/ 1/24		/ 1 Oc	eana County Sur	rveyor		.16	11. C. C. C. S. C.	-
M	n/		4/			190		