SURVEY & REMONUMENTATION

JAN 11 1999

SECTION

100861 STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR DECORP

	LA	MD COKNER RECOR	DATION CERTIFIC	CATE ACCULIATED FOR KECOMD
For corners in	•	filing Requirement of A	ct 74, Mich. P.A. 19	970 28 DEC 1998 4:33:04 PM
Oceana (County)	Located In:	Corner Code #		JOSEPH E. MERTEN REGISTER OF DEEDS
1. Public Land Survey	T15N T T	R 16W I-4 R R		VEDIFIEW OF DEFINE
Property Controlling in Section Miscellaneous Property in Sec.		R		Register of Deeds Stamp & File Number
4. Lat No. Ra	acorded Dist			
5. Private Claims				ABCDEFGHIJK T.
				֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓
J. Randolph Hepw	orth	May 21, 1998		3 3 2 1 1
ocuiromente et D.A. 74 Mil	, in a field survey o	n, 19 do	hereby state that under	4 - 7 - 8 - 9 - 10 - 11 - 12
Inited States Department of that the corner points mentic loard of Land Surveyors o ecovered, found as expresse	the Interior, Bureau of Land oned in lines 3, 4 and 5 about by a Decree of a Court dibelow:	ired in the current manual of sul Management or by a decree of we were in conformance with the of Law; established, re-estal	rvey instructions of the is Court of Lew and /or e rules of the Michigan blished, monumented,	5
IOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				9
				10 30 29 28 27 26 25
				11 12 31 32 33 34 35 36
.				13
		ories and/or subsequent res		•
I-4 Quarter Corne	er Common to Secti	ons 10 & 11 T15N, F	R16W Elbridge	Township
GLO SET POST	10" Sugar N30°W 1	5' 12" Sugar N88°E	18'	Oceana Annala n
OCRC WITNESS BO	· · · - · - · · ·	"T" Iron post		Oceana County Remonumentation Peer Group Reviewed & Approved
8" Elm R. E. A. Pole	W. 36.2' N45°E 92.8'		-	Date: 10-13-98
Butternut	Due W. 60.5'			JRN
LCRC# 100446, R. Hepv Center Roads I P Pole	N-S & E Old occup 75°AZ 85.85'	Set 1/2" X 2' fron ation line to W		J. Randolph Hepworth Oceana County Surveyor
Sign Post Tw 16" Maple Tel J. Box Stak	278°AZ 20.85' 20°AZ 126.18 e 145°AZ 55.5'	1		
B. Description of cor	ner evidence found a	nd/or method applied in	restoring or reestal	blishing corner.
I found in the centerl occupation line to the witnesses are gone. fill/cut transition area	ine of a north-south e west a JRH 1/2" Iro This corner was re- . No other ferrous n	road and in the on and cap at the surfacterstablished by me in 19 netal stake was detected	centerline of a e as described in L 191 by the collatora d. I accept this in	road to the east and on an old CRC No. 100446. All OCRC all local evidence. Road bed is in a con as best available evidence of the to believe that the corner should be at
C. Description of mo Seta 4"x20" Harrison Cas	ทนment for corner an t Iron Monument, stamped	d accessories established I "County Surveyor" and "264	to perpetuate locat 57" above the JRH Iron	ing the position of the corner. which was driven down.
60d spk SE Fa 60d spk SE Fa 60d spk NE Fa	ace 10" Ash	70°az 12°az 327°az	85.86 161.12 51.58	EDM EDM EDM
center	road name sign post	277°az	20.96	EDM

J. RANDOLPH Date

SURVEYOR

NO.

26457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS. JAN 20, 1971
REVISED JAN, 1983
REVISED JAN, 1983
REVISED OCT., 1996 HERWORTH November 10, 1998 Signed by 26457 Surveyor's Michigan License No.