## SURVEY & REMONUMENTATION

JAN 1 1 1999

**SECTION** 

STATE OF MICHIGAN COUNTY OF OCEANA

RECEIVED FOR RECORD

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

28 DEC 1998 4:38:04 PM

		l		
ated In	Corner Code #		JOSEPH E. HERTEN	
atod III.	Comer Code #		REGISTER OF DEEDS	
TR TR TR	<u>I-9</u>		100892	<b>&gt;</b>
TR			Register of Deeds Stamp & File Nu	mb
at		_	A B C D E F G H I J H  2 6 5 4 3 2 2	<u> </u>
7 1970, the corner point refore as required in the ureau of Land Manage 6, 4 and 5 above were to be of a Court of Law	nts mentioned in lines 1 and ne current manual of survey li ement or by a decree of a Coo in conformance with the ruler r; established, re-establishe	2 above were in nstructions of the urt of Law and /or s of the Michigan	4 7 8 9 10 11 5 6 18 17 16 15 14 7 8 19 20 21 22 23 9 10 30 29 28 27 26 11	
CTIONS 22, 23, 26 &	27 T16N, R18W		13	3
" 3/4" gas pipe with vak N80°E 60'  1, CM Stover, 1966 11/72, Fd 1" Pipe 12" W Pi Survey, 11/72, Wit 102, 16923, 7/11/72, Wit 102, Hepworth #26457, 10 1, 1/17/92, Fd 1¼" Pip 1100102 1th #26457, 6/24/94, 1th #26457, 8/14/96	Blaze & Nail & L.N. Tag ine N82°W 53.65' nesses from LCRC 100102 Pipe 0/88 be See LCRC # 100460 Same As LCRC # 100460		Oceana County Remonumentation Peer Group Reviewed & Approved Date: 12-10-98  J. Randolph Hepworth Oceana County Surveyor	
	Auguidd survey on T R T R T R T R T R T R T R T R T R T	TOTAL REST TO	TIGN R 18W I-9 TIR R TIR TIR TIR TIR TIR TIR TIR TIR TI	TIGN RISH IT 9  TOORS 32  TOORS 33  TOORS 34  TOORS 34

I found a 1 1/4" Well Point Pipe well-rotted with 5' steel fence post beside it. All LCRC 100102 witnesses by Barnett are still standing, but all nails and brass tags are not visible. No Salisbury witnesses were found, nor did I find a Pipe as described by Salisbury. I believe that this pipe was probably set by Stover for SAND & SURF Subdivision in 1963.

I accept this Pipe as being a careful and faithful perpetuation of the position of the original corner. No evidence is known to me that would lead me to believe that the corner should be at another location.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 4"x20	0" Harrison Ca	st Iron Monument, stamped "C	ounty Surveyor" and	"26457" above the W	ell-Point which wa	s driven down.
	SW Face	10" W Oak	341°az	19.86	EDM	1888 F. W. W.
60d spk	NW Face	10" Maple clump	72°az	38.75	EDM	MICH IN
60d spk	N Face	16" Oak	116ºaz	19.27	EDM	1 ( L 01 1110/1/2)
60d spk	E Face	6" Maple	205°az	16.17	EDM	CAR
60d spk	S Face	14" Pine	279°az	53.61	EDM	J. RANDOLPH
						<b>HEPWORTH</b>
						LAND
		1 1	/			SURVEYOR
	.//					NO.
		1160 Hours				<b>分・26457 ・</b> ◇
Signed by	11-	myn / saug	E	Date	Decembe	r 214, 1998
Surreyor's	∕ Michigan Lice	ense No. 26457	7			WILL SO EARD
onive you a	Michigan Lice	2043 A				a think the the