## SURVEY & REMONUMENTATION

JAN 1 1 1999

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

28 DEC 1998 4:33:58 PM

JOSEPH E. MERTEN REGISTER OF DEEDS 100867
of Deeds Stamp & File Number
D E F G H I J K L 5 - 4 - 3 - 2 - 1 - 1 - 12 - 12 - 14 - 13
-20 - 21 - 22 - 23 - 24 -29 - 28 - 27 - 26 - 25 -32 - 33 - 34 - 35 - 36
Randolph Hepworth cana County Survevor

B. Description of corner evidence found and/or method applied in

This corner falls in a road intersection that is 6'-8' above original ground grade. The Blass Iron was not found; nor are any Blass witnesses standing. I would guess that the Blass Iron is probably 6'-8' below present grade but is not detectable. In 1986, I reset this corner using Blass survey Information from the Consumers Power Co. survey by angle and distance using G-11, H-11, I-11.

I accept this Iron as a careful and faithful re-establishment of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

C. Describuon o	I IIIoiiaiiione ioi				
Set 4"x20" Harrison 60d spk 60d spk 60d spk 60d spk 60d spk	Cast Iron Monument NE Face F Face	t, stamped "County St 20" Basswood Power Pole/Transf Power Pole 10" R Pine	urveyor" and "26457" repla 290°az 165°az 39°az 61°az	acing the 1/2" 62.60 146.94 45.67 75.51	Iron EDM EDM EDM EDM



	*******		
Signed by	Date	November 10, 1998	
- ·			