MEAN SERVICE

STREETS & HENCON WELLIAMS.

STATE OF MCHOUS

LAND CORNER RECORDATION CERTIFICATE

10000

Î. O.

i itanorii

REPWORTH

7.

	Filing Requirem	ent of Act 74, Mich. P.A. 197	o '96 DEC 1	9 A11:15 (2)	
r corners in Oceana (County)	Located In:	Corner Code #	0	~~~	
10001197	<i>;</i>		REGISTER O	energe view	
Public Land Survey	T 16N R16W	$(M-7)\sqrt{}$	> VEOIDIEIL	r utens	
	T <u>16N</u> R <u>15W</u>	A-7			
	T R				
	T D				

2. Property Controlling Т _ R _ T in Section S Т S 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section

J. Randolph Hepworth, in a field survey on October 18 ,19 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current

manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

_ , Recorded Plat _

A. Description of original monument and accessories and/or subsequent restoration:

M-7 Corner Common to Sections 13 & 24 T16N, R16W Crystal Township A-7 Corner Common to Sections 18 & 19 T16N, R15W Colfax Township

SET POST 6" Beech N23°W 61' 10" Beech N59°W 23' Book B, Pg 26; F. Wetmore, 1901; "Oak Stake no iron." Book C, Pg 22; F. Wetmore, 1901; Same as Book B, Pg 26. Book B, Pg 42; F. Wetmore, 1901; Same as Book B, Pg 26. Book C, Pg 36; F. Wetmore, 1902; "Old Cor. See Record Sec 13." Book C, Pg 24; F. Wetmore, 1902; "Old Cor. See Record Sec 13." Book B, Pg 36; F. Wetmore, 1902; "Iron Stake set by J. Bean 1883. See Record Sec 13."

Book C, Pg 38; F. Wetmore, 1902; Same as Book B, Pg 36.
Recorded Survey Jkt # 162 12-22-75 C. Cole #17615 See witnesses on LCRC # 100205

LCRC # 100205 8-24-77 Clinton Cole 17615 Fd 3/4" pipe

P. Pole S55°E 63.53' P. Pole S48°W 45.36' Anchor Pole N33°W 58.41'

LCRC # 100350 6-26-86 K. Ross # 17634 Found 3/8" X 3/8" X 18" Pointed pin on top of a 1 1/4" by 36" pipe, and determined this to be in its exact location for the NW Corner of the Section. Fd Clint Cole's 1977 witnesses.

Replaced 3/8" X 3/8" X 18" Pointed pin on top of a 1 1/4" by 36" pipe with 5" X 5" X 36" conc. mon 1' below road surface. Mon. has brass cap stamped as follows: T16N, R15W, S18, S13, S24, S19, 1986, LLS 17634.

P. Pole S56°E 63.37'

4. Lot No. 5. Private Claims

P. Pole S53°W 45.38'

Guy Pole N31°W 58.45

12" Oak S8°E 70.83'

Recorded Survey Jkt # 380 6/26/86 K. Ross # 17634 Found 3/8" X 3/8" X 18" Pointed pin on top of a 1 1/4" by 36" pipe, replaced with 5" X 5" X 36" conc. mon 1' below road surface. Mon. has brass cap. Witnesses are same as LCRC # 100350.

Recorded Survey Jkt # 382 6/26/86 K. Ross # 17634 See Jkt # 380, Same info & witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found in the centerline of an east-west asphalt road and 6' east of the centerline of north-south gravel road at 14" deep a 5" square concrete monument by K. Ross, LS 17634 as described in LCRC NO. 100350. All LCRC 100350 witnesses are standing and measure OK.

This monument was accepted as the best evidence of the corner and was accepted as being a careful and faithful perpetuation of the original corner. No evidence is known to me that would lead me to believe that the corner should be in another location. This monument is a substantial monument and was not replaced.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

	4 4 7	Carner Cameran	ta Cantinaa 12 0 0	TICK DICKE	Taurantia	- '	• • =
1	M-7	Corner Common	to Sections 13 & 24	T16N, R16W C	thatat tomusuib		_
			to Sections 18 & 19		Colfax Tow		Oceans County Remonumentation
	5" X 5" X	36" Brass cap co.	ncrete monument s	tamped as follows:	T16N, R15W, S	\$18, S13, S24, S19, 1986	LLS 17634, Peer Group Reviewed & Approved
		NE Face	Power Pole	121°az	63.40	EDM	Date: 11-13-96
4	40d spk	SE Face	Power Pole	224°az	45.32	EDM	Date:
4	40d spk	SW Face	Guy Pole	325°az	58.41	EDM	INH-
1	60d spk	W Face	12" Oak	168°az	70.78	EDM	J. Rangolph Hepworth
(60d spk	NW Face	20" Oak	62°az	82,60	EDM	Oceana County Surveyor
- 1	USGS Be	enchmark Mon "TT	13 TEX 1980"	43°az /	42.37	EDM	oranty carveyor
		10	11/11/11	16		Date Dece	mber 5. 1996
cris.	anad hu	// -	161 F N	40/11/15/11/11/11		1 24 24 (7 27 2 2	:RBJC:1 .J + 1.2.7 U

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No.__ 26457 REVISED MAY 14, 19

REVISED JAN., 1983