٦F"

Ogemaw County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FEB 2 4 2000

For corners in		1	SECTION
Ogemaw Located (County)	in: Corner Code #		
1. Public Land Survey	T22N R01E K-7 T R T R	- - - 1 100111 ABITA (100110 1012) ABIT (618 11815)	
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	T R	Handa Muzik, Ogemsw Co. Register Register	Page: 1 of 1 12/27/1999 09:09A SURC 9.00 L-3 P-295 of Deeds Stamp & File Number
4. Lot No, Recorded Plat_			
5. Private Claims		1 A B C	DEFGRIJKIN
that under requirements of P.A. 74, Michigar in lines 1 and 2 above were in conformance with the current manual of survey instructions of the Bureau of Land Management or by a decree of mentioned in fines 3, 4 and 5 above were in co of Land Surveyors or by a Decree of a Court of recovered, found as expressed below:	th regulations and rules therefore as required united States Department of the Interior, If a Court of Law and/or that the corner point of the Michigan is the Michigan in the rules of the Michigan is set the Michigan is set to	ints 6 19 Board	-8 - 9101112 -1716151413 -2021222324 -
NOTE: Not more than 2 corners, all i on this certificate	n the same town and range, may	be recorded 9 10 30 11	-29 28 27 26 25 1
A. Description of original monument ar K-7: GLO by B.F. Hall, 1848, post N33E 22 6" Beech N55W 10 6" Beech LCRC by A.V. Courtright, 1973, found 1/2" fron West 20.57 Fence post East 25.83 Fence post S65E 52.23 12" White Birch LCRC by J.L. Wilcox, 1966, found 1/2" fron rod S39W 70.54 Southeast Cor of house foundation S63E 51.42 9" Birch Due East 25.60 Fence Cor Post Survey by L. Cavanagh, 1974, found 1/2" bar East 33.08 Capped fron Survey by R. Higgins, 1977, found 7/8" fron No witnesses Survey by D. Ledy, 1984, found 1/2" rod S39W 70.54 Southeast Cor of house foundation S63E 51.42 9" Birch Due East 25.60 Fence Cor Post	Survey by D. Ledy, 1985, found 1/2" rod No Witnesses Survey by R. Higgins, 1961, no material Witnesses Survey by R. Higgins, 1976, found 7/8" ber Survey by R. Higgins, 1976, found 7/8" ber Survey by R. L. Miller, 1998, found ber Survey by R.L. Miller,	S84W 73.09 Northeast Cor Trail Survey by T. Lapham, 1985, found 1/2" fron S88E 28.51 Fence Corner S39E 52.19 4" Ash B17W 102.20 Utility Pole S83W 73.15 Northeast Cor Mol Home Survey by J. May, 1999, found 1/2 fron N89E 61.22 5" Twin Poplar S57E 51.86 9" Birch S37E 52.22 7" Elm S24W 102.08 Utility Pole Survey by D. Ledy, 1989, found 1/2 fod S39W 70.54 Southeast Cor of house foundation S63E 51.42 9" Birch	t C
Description of corner evidence foun K-2: No Gt O survey evidence found. Fruin	S20W 102.84 Utility Pole ad and/or method applied in restorin d capped iron reset from 1999 road plan w 8 matches 1966 through 1999 records ex	vitnessas. Found 1 - 1996 witness and	1 1 - 1973 witness that match
Description of monument for corner IK-7: Set 5/8"x38" rerod w/aluminum remonents 60.93 6" Twin Poplar 560E 51.68 12" Birch S20W 102.84 Utility Pole 564W 73.09 NE Cor Trailer gred by	r and accessories established to pe	rpetuate locating the position of \$32E 52.25 & Ash	A CARREST OF THE STREET

27595

erveyor's Michigan License No.