SURVEY & REMONUMENTATION

DEC 1 3 2000 LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

		~	Ŧ.	0	A 5
্স	Ε,	U	9 1		ŭ ∕v.

	r corners in ceola		Located in:	Corner Co	de#				(as	£ ,	8	끊
Public Land Survey			T_17 N	R8W	D-7				K		NOV-	SCEO SCEO
			T	R					Ç	6	-2	別を
			Т	R					Or	:	¥	
	•		T	R					Ž		당	EEDS NTY
2.	Property Controlling in Section	s	T	R					()	\	N)	ഗ
		s	T	R		Registe	rof∏	eeds)	Stam	n & F	ile Nu	ımber
3.	Miscellaneous Property in Sec.	S	T	R		rtegiste						
		s	тт	R				~		. TY 1		7 T M
4.	Lot NoReco	rded Pl	at			A	В	3 10 1	SKC	; H	JF	LM
5.	Private Claims		<u> </u>			1 2	6	5	4	3	2	1
ho	Robert L. Wetherell, in a ereby certify that under re	equirem	ents of P.A. 74.	Michigan P.A.	of 1970, the comer	3 4	7	8	9	10	11	12
po ru	oints mentioned in lines i	1 and 2	above were in co current manual c	ontormance w of survey instru	ith regulations and actions of the United	5 6	18	17	16	15	14	13
St	ates Department of the	Interior,	Bureau of Land	Management	or by decree of a	7			24	22	22	24

Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

P	RE	; p r	FU	, II 1	J	1, 171	
1 2 3	6	5	4	3	2	1	
4	7	8	9	10	11	12	
5 6	18	17	16	15	14	13	
8	19	20	21	22	23	24	
9	30	29	28	27	26	25	
11 12	31	32	33	34	35	36	
13			<u> </u>				

D-7 - 1/4 corner common to Sections 17 & 20, T17N, R8W.

A. Description of original monument and accessories and/or subsequent restoration: 1980 - R.L. Wetherell, LS 24624

1848 - O. Lyon, G.L.O.

#1 - 18" Beech N33°E 40 Links

#2 - 17" Beech S56°W 21 Links

1891-1904 - Trumbull

Remonumented T17N, R8W with 3" Clay Tiles.

Identified by stake and stone OBT.

#3 - 14" Hemlock N11°E 60 Links

#4 - 36" Pine Stump S0°45"E 83 ½ Links

1980 - P. Lapham, LS 9433

L.C.R.C. - Liber 2, Pg. 144. "Found steel fence post in stone pile".

#5 - 12" Cherry S60°W 14.33'

#6 - Fence corner N85°W 24.09'

#7 - Maple Clump N20°E 24.77' #8 - Fence corner S50°E 45.08'

1982 - E. Farrier, LS 24594

Found 1" Rod, set 1/2" Iron with cap.

Survey recorded L. 374, Pg. 408.

Same witnesses as P. Lapham.

#5 - 16" Cherry S70°W 19.95'

#9 - Fence Post N7°W 29.03'

#7 - Maple Clump N10°E 19.20'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found an old iron fence post (24" Long) surrounded by stones (corner was approximately 3 feet below ground surface in fill area for drive to the North. I also found a ½" capped iron (LS 24594) N52°06'50"E, 6.25 feet from the fence post and stones. I excavated the entire area with a backhoe to a depth of 5 feet more or less, no other evidence was found. The iron fence post was in line with old fence to North and 3 feet more or less South of fence to West. I accepted the iron fence post as the correct corner and removed the ½" Capped Iron. I measured N89°12'04"W a distance of 2619.42 fect west to the Section corner.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Found in good condition, #6 Down, #7 Dead, #8 Down, #9 Down.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I replaced the iron fence post with a 1 x 18" Iron Pipe with Osceola County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

14" Maple in clump S40°W 26.14' (60d spike E. side)

22" Cherry S74°W 14.73' (60d spike S. side) #5

16" W. Pine Due West 71.80' (60d spike N. side)

18" Maple N15°W 77.12' (60d spike W. side)

8" Cherry N65°E 49.57' (60d spike N.W. side)

APPROVED LAND CORNER P.A. 345 OF 1990

Osceola County

10-31-

Surveyor's Michigan License No. 24624

Date November 1, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983