

DEC 1 3 2000

oeuti()Nį LAN	ID CORI	NER I REQUIR	RECO REMENT	RDATION C OF ACT 74, Mich.	ERT P.A. 1	1 FIC 970	AT	E				
For corners in Osceola		Located i	n:	Corner C	code#	1			~	Thorna	00 HAY	REGIS	OSCE
1. Public Lar	d Survey	T <u>17</u>	<u>N J</u>	R8W	F-11	_				K.	<u>-</u> 5	[1]	("")
		<u>T</u>		R		_				13/22		promp) m
		<u>T</u>		R		_			,,		PM 2: 50		NTY NEW Y
		T		R	_	_				A	S	5 8	n n
2. Property Contr		Т	R			_ [
in Section	s	T	R			_ _R	egiste	r of D	eeds	Stam	р&F	ile Nu	umber
3. Miscellaneous		T	R			_					•		
Property in	Sec.	<u> </u>	R				,	. D (n r	7 F C	. H 1	ı ı K	C L M
4. Lot No 5. Private Cl	Recorded I aims	Plat				_	1 [2]	6	5	4	3	2	1
I, Robert L. We	I, Robert L. Wetherell, in a field survey on March 22, 2000, do						3	7	 	9	10	11	
hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the comer points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented,						5	18	17	16	15	14		
						7	19	20	21	22	23	-	
						ecree	9 10	30	29	28	27	26	25
recovered, found as expressed below:						11 12	31	32	33	34	35	36	
F-11 - ½ Corn	er common to S	Sections 28 &	د 33, T1	7N, R8W	7		13		1	1	l		
						storatio	on:						
A. Description of original monument an 1848 - O. Lyon, G.L.O.			<u> 1966 - J. Lazarowitz</u>				1996 - R.L. Weineren, 127 24024						
			Developed plat of "Lake Miramichi Sub."				" L.C.R.C Liber 03, Pg. 185 Found 5/8" Iron in 3" Clay Tile.						
			No mor	o monument or accessories given.			#5 - 6" W. Birch N85°E 25.39'						
1001 100	A O Tomplo	Co Sur									∃ 16.0		
1891-1904 - A.O. Temple. Co. Sur. "Identified by measurement".				#7 - 4" Cherry N10°E 19.9'			.91						
Set 3" Cla		•					#8 -	4" H	ackbe	erry S	70°W	18.8	7'
#3 - 36" P	ine Stump N3½°	E 205 Links											
	ple N41¾°W 53												
						_							

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a 5/8" iron in center of a 3" clay tile with cinders. I also found a 1" pipe with an Osceola County Brass Cap which was N6°E 10.0' from the clay tile. I accepted the clay tile as the correct corner and removed the 1" pipe with cap. The corner is in line with old fence to the North. It is 25 feet South of a corner fence post and 22 feet North of an East and West fence line. There appears to be an old road bed running East and West. I measured the following distances: 2645.01 feet West to Sec. Cor. and 2643.88 feet to Sec. Cor.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition, #8 Found in good condition.

<u></u>	Description of monument for corner and accessories established to perpetuate	locating	the position of the corner:
C.	I set a 1" x 18" Iron Pipe with Osceola County Remon Cap, in the center of the 3" C	Clay Tile,	and is accepted as a careful and
	faithful reestablishment of the position of the original corner.		0 P M/64

Tailing reestablishment of the position of the original control		
6" W. Birch N85°E 25.39' (60d spike in N. side) 5" Poplar S37°E 16.03' (60d spike in S.W. side)	APPROVED LAND CORNER PA 245 05 1990 Cacada County	
•	Capadial Coarty	
4" Cham. N100E 10 05' (60d spike in E. side)	A 111	

4" Hackberry S70°W 18.87' (60d spike in N. side) 4-20-2000

Date April 25, 2000

N STATE BOARD OF LAND SURVEYORS, JAN26, REVISED MAY 14, REVISED JAN, ADAPTED FOR WORD PROCESSING JANUARY, FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUR

LAND

SURVEYOR

NO 24624