

- FEB 1 6 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	i ming i to	quitotitotic of Flot 7-4, 1910ii. 1	1		
Osceola (County)	Located In:	Corner Code #		APPROVED LAN P.A. 345 OF	
1. Public Land Survey	T17N R10W T R T R T R	F-9	4	Osceola Co 12 May 1 Manthur	unty 1998 M. Wing
Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		Re	gister of Deeds St	amp & File Number
4. Lot No, Recorde	ed Plat				
5. Private Claims			2 - C	3 C D E F C	3 H I J K L N
I, <u>Matthew McClung</u> in a field survey on <u>11-2</u> , 1998 do hereby state that unde requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /o that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:			t under 4 vere in s of the and /or 6 -1 chigan	8 17 16 9 21 17 16 17 16 17 16 17 18 17 18	
NOTE: Not more than 2 comes on this certificate.	s, all in the same town and	range, may be recorded	9 10 3 11 12 3	32 33	
1838. Set wood po Beech 30" N10 B. Ash 16" S2 From 1891 to 1904 program, in which most part, a 3" g at each governmen tile per corner,	er was set by st 40.08 chair E 19 lks. 6E 20 lks. approximately surveyors Ten lazed tile fil t set corner i	deputy surveyor Jo	nad a rem did the from a fo here were ntinued o	nonumentati work. For orge, were supposed	on the placed
•		f asphalt road. Ex	_	:o 26" rem	oving
1/2 X 24" rerod a 22" steel rod, an deeper with hole, below surface. Co	nd found top o d magnetic loo placed Osceol rner is in fer	of Steel rod. Excar cater showed more in la County Monument nce rows North & Si ide of road has be	vated to metal bel in posit outh, 1'	48", remove. low. Unable lion top ro South of	red to go
				TE-	OF MICHIGA
C. Description of monument for	r corner and accessories	established to perpetuate locating	the position of	At IS'	MATTHEW ATTHEW MCCLUNG
a 1" pipe 18" in 6" Ash Treated 6" mapl	length. w/nail N12E 35 6" Corner fer	Monument, which is 5.35 feet. O.B.P. nce post NO5E 33.1 w/nail N75E 96.6 feet.	5 feet.		SURVEYOR S NO. 13037 C
Signed by Multiple Surveyor's Michigan License No.	M Clevej 5 1303	37 Date	1 Ve	1 1898	

FEB 1 6 1999

SECTION

OSCEOLA COUNTY REGISTER OF DEEDS

98 DEC - 1 PH 4:58

Many Careford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 1 of the townships have been recorded in the County Survey

Richmond Twp. Book, Front pages, #1. Act 74, Liber 2, page 344. Gray Iron pin. Found Steel rod 3' deep, raised with 6" Maple NO6E 41.81 Dis. F-9 to G-9 = 2641.6

1/2" rebar.
5" Maple (in clump) Az 60
4" Ash Az 05 35.00'

6" Ash Az 225 47.19°

Act 132, Liber 316, Pages 542 & 543. Found iron. 5" Maple in clump N60E 96.68° 4" Ash N05E 35.00° 6" Ash N45W 47.19° Dis F-9 to $G-9 = 2636.40^{\circ}$