## SURVEY & REMONUMENTATIO

DEC 13 2000

## LAND CORNER RECORDATION CERTIFICATE

SECTION

For corners in

Osceola

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

Corner Code#

Located in:

1.	Public Land Survey		<u>8 N</u>	<u>R8W</u>	<u>C-9</u>				• :	C	<u> </u>	교용 -
		т		R	ì				<i>r</i> .		, 	2m 30
										<u>-</u>		
		<u>T</u>		<u>R</u>					* *		ACAM Comm	유민
		<u>T</u>		<u>R</u>						ا ،	ن پ	
2.	Property Controlling	S T		R					2. 15 1	•	 	(n)
	in Section	<u>S</u> <u>T</u>		<u>R</u>		Registe	r of C	)eeds	Stam	np & F	ile Nu	ımber
3.	Miscellaneous	sT		R		regions				.,.		
	Property in Sec.	sT		R								
	Lot NoRecor	rded Plat		<u></u>			B	CDI	EFC	H	J	LM
5.	Private Claims	S				1 2	6	5	4	3	2	1
I, F	obert <u>L. Wetherell,</u> in a	field survey on A	<u>pril 21.</u>	<u>2000</u> , do	(4070 #	3	7	8	9	10	11	12
noi	nts mentioned in lines 1	1 and 2 above we	re in co	. 74, Michigan P.A. of 1970, the corner in conformance with regulations and hual of survey instructions of the United Land Management or by decree of a			18	17	16	15	14	13
Sta	tes Denartment of the l	Interior. Bureau o	f Land N				19	20	21	22	23	24
Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decre Of a Court of Law; established, re-established, monumented, re-monumented,						8 9	19	<b></b>				
						10	30	29	28	27	26	25
recovered, found as expressed below:						11 12	31	32	33	34	35	36
	) - Section corner comm					13		<u> </u>	<u> </u>	<u></u>		
Α.	. Description of original monument an 1848 - O. Lyon, G.L.O. #1 - 24" Hemlock S51°E 22 Links #2 - 10" Beech N7½°W 13 Links  1894 -1904 - Temple/Trumbull/June Remonumented T18N, R8W with 3" Clay Tiles with Cinders.			- M.McClung by recorded Lid d Tile and Iron 8" Maple N50 8" N. Pine N50 - K. Ostling d Tile & Iron 23" R. Pine N50 12" Pine S450 8" W. Pine S55	1983 - R.L. Wetherell, LS 24624 Survey recorded Liber 405, Pg. 639 Same accessories as Ostling in 1978.  1987 - M. McClung, LS 13037 Survey recorded Liber 477 Pages 99, 100 and 104. Same accessories as Ostling.							
В.	Description of corne I found ½" Iron in Ti line with road East at	ile with old wood	d and/o stake al	or method applometric properties.	plicd in restoring of mer is 7 feet West of	reestabli centerline	ishin e of l	<b>g cor</b> Vorth	ner: and S	South	road a	and in
	Condition of the accordance condition, #5 Found	essories are as fol in good condition	lows: # 1, #6 Fo	#1 Gone, #2 G und in good c	one, #3 Found in goo ondition.	d conditi	ion (1	√67°I	E), #4	Foun	d in g	good
C.	Description of mon I replaced the ½" Ro reestablishment of th	d with a 1" x 18"	Pipe wi	ith Osceola Co	ablished to perpetus ounty Remon Cap, an	i <b>te locati</b> d is acce	ing tl pted	ie po: as a c	sition areful	of the	e cor faithf	ner: ul
	23" P Pine N23°W	48 18' (60d spike	E. side	) #4							有严 網	120
	23" R. Pine N33°W 48.18' (60d spike 1 22" R. Pine S47°E 108.54' (60d spike 1			N.E. side) #5 APPROVED LA?			ER		^	المم المجاري	ئۆچى ئىدىك	Contraction of the
	11" W. Pine S55°W 18" Maple S31°W 7.	E. side)	E. side) #6 P.A. 345 (			-		5 1 189 2 42 A		OSEF THE	AT L. N	
	-0 1.vabye 000 1 11 1.	- \	,		(1 ) ( )				. 1			

Surveyor's Michigan License No. 24624

Date August 22, 2000

2000

24 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999