

FEB 2 5 1994

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in COMMS	SION Filing Requi	rement of Act 74, Mich. P.A	. 1970
Oseenja	Located In:	Corner Code ##	•
Public Land Survey	T <u>18N</u> R <u>9W</u> T R	A-6	APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County
	T R T R		Matthew M. Church
Property Controlling     in Section	S T R S T R		8 Nua (993
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
		l	
4. Lot No, F 5. Private Claims	Recorded Plat		ABCDEFGHIJKL
			2 6 5 4 3 2
			3 4 7 8 9 9 10 11
	ຸກ£n a field survey on <u>Nov</u>		3, 5
	quirements of P.A. 74, Michigan P.A n conformance with regulations a		
current manual of survey instr	uctions of the United States Depa	rtment of the Interior, Bureau of La	ind 7
above were in conformance wi	a Court of Law and/or that the corn th the rules of the Michigan Board	of Land Surveyors or by a Decree o	of a 9 20 21 22 23 1 2
Court of Law; established, expressed below:	re-established, monumented, re-	monumented, recovered, found	as 10 30 29 28 27 26 2
NOTE: Not more than 4 c	orners, all in the same town a	nd range, may be recorded	"
on this certificate.			12 31 32 33 34 35 3 13
The original 1837. Set woo Beech 8" Beech 8" The corner wa piece of gas The corner wa pipe, with two B. Description of corner e Found 1 1/4" brass cap as below road su Pipe is real Monument 8" be pieces of pipe	d post 40 chains for S48W 28 lks.  N53W 20 lks.  s recorded in Lincopipe with two with second and/or method pipe at road surfact and removed old, hit it on pice at depth of monuments.	deputy surveyor Jorom South  oln Twp. Book on Nesses. The cemeter  Cedar Twp. Book 19 asswood tree has fapplied in restoring or reestable, in centerline gertificate. Excepipe. Found no evik and broke pipe is at position of olement.	Jov. 30, 1904 as, Corner 6 by monument is still good.  Nov. 1931 as: Corner 8, Sallen (continued on back) lishing comer:  of road. Did not find eavated to a depth of 20" dence of another corner. Into. Set Osceola County depipe. Reset the Twp  MATTHEW  A. McCLUNG LAND SURVEYOR NO.  ting the position of the come2037  "house our months of the come2037 "house our months of the come2037 "house our months of the come2037
Corner M-6. Os  1" pipe 18" in  Cemetery  18" Maple  SW corner  Property  NW corner	sceola County Monum n length. Flag Pole N35E 61 e S20E 65.15 feet. r of Traux grave ma corner west 33.0 c r of Marsh grave ma	ment, which is a 3 .0 feet. OBT previously re arker N60E 57.8 fe feet. Cannot read arker S77E 49.6 fe	corded as S20W. et. OBTie No. on cap.
Signed by Matthe	w McCling e No. 1303		vember 28, 1993
Surveyor's Michigan License	e No1303	/	ORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1

OSCEDLA COUNTY REGISTER OF DEEDS

93 DEC 16 PM 4:48

but is still visible.

The distance was measured in 1975 and found to be 2610.76, compared to 2611.0 as recorded on page 52.

A PA. 74 certificate was recorded by my self in 1975, which I stated I set Brass Cap, which I did not find and don't think I set. The three witnesses are visible.