SURVEY & REMONUMENTATION:

DEC 1 3 2000

LAND CORNER RECORDATION CERTIFICATE

SECTION

For corners in

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

	ceola		Located in:	Corner Coo	le#						300	1313	<u>G</u>	
1.	Public Land Survey		T_18 N_	<u> R9W</u>	E-9				1.		<u></u> 1	: Ti	2	
			Т	R							<u> 1000</u>	1,1	<u>(</u>	
			т	R					- \		∵ Ç	; ; [[]) C. 1프	
			Т	R						A.	i C	• 12 • (*	it was	
2.	Property Controlling	Q	 T	R						i,				
۷.	in Section													
		<u>S</u>	T	R	<u>`</u>	Registe	er of [Deeds	Stan	ıp & F	ile Nu	ımber		
3.	Miscellaneous Property in Sec.	<u>s</u>	T	R										
1	Lot NoRecor	S_	т	R			A B	C D I	7 F G	ен 1	JK	LM		
	Private Claims					1			4	3	2	1		
	ober <u>t L. Wetherell,</u> in a					3	6	5						
poi	eby certify that under rents mentioned in lines 1	and 2 ab	ove were in	conformance with	n regulations and	4 5	7	8	9	10	11	12		
rule	es therefore as required tes Department of the I	I in the cu	rrent manua	al of survey instruc	tions of the United	6 7	18	17	16	15	14	13		
Court of Law and/or that the corner points m in conformance with the rules of the Michiga				entioned in lines 3, 4, and 5 above were			19	20	21	22	23	24		
Of a Court of Law; established, re-establish recovered, found as expressed below:			stablished, ı	d, monumented, re-monumented,			30	29	28	27	26	25		
100	overeu, iounu as expre	3300 0010				11 12 13	31	32	33	.34	35	36		
A. Description of original monument and a 1838 – J. Hodgson, G.L.O. 15 #1 – 10" Beech S42°W 5 Links (S #2 – 8" Ironwood S77°E 11 Links U Undated Co. Surveyor Twp. Book Pg. 5 #3 40" Pine N8½°W 96.8' L #4 – 30" Pine N75°E 71.4' F Undated Co. Surveyor R Twp., Book, Pg's 56 to 58 "Gun Barrel" ##				& 29, T18N, R9W ccessories and/or subsequent restorate 174 - C. Cole, LS 17615 curvey rec. L. 353 Pg. 362). Sed cor. to set 1/16 cor. South to accessories given. 178 - R.L. Wetherell, LS 24624 c.R.C L. 02, Pg. 60. cound gun barrel with stone 12' west. eplaced with 4" Concrete Monument. 10 - 4" Oak S64°W 20.00' 10 - 14" Maple N37°W 27.68' 11 - 3" Cherry S51°E 9.75'			1994 R.L.Wetherell, LS 24624 Unrecorded Survey. #12 - 8" R. Oak S66°W 19.94' #13 - 8" R. Oak S33°E 24.31' #14 - 3" R. Oak N30°E 39.71' #10 Maple N34°W 28.22'							
В.	 B. Description of corner evidence found and/or method applied in restoring of reestablishing corner: I found the 4" x 36" Concrete Monument I set in 1978. Corner is 9 feet more or less South of two track road running East and West. Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found Stump, #4 Found remains of stump, #5 Found Stump, #6 Gone, #7 Measured 2651.1', #8 Measured 2642.5', #9 Found in good condition, #10, Found in good condition, #11 Found in good condition, #12 Found in good condition, #13 Found in good condition. 													
C.	Description of monu I accepted the 4" Cor reestablishment of the	ıment for ıcrete Mo	corner and	d accessories esta substantial mark	ablished to perpetua	te locati	ing tl	ıe pos	i tion	of the	e corr thful	ier:		
	10" R. Oak S66°W 1 20" Maple N34°W 20 10" R. Oak S33°E 24	8.22' (600	i spike N.E.	side) #10	APPROVED LA P.A. 345 Osceola	OF 1990		R			130) 130) 1417)	PERI VEN	L. ELL	
5" R. Oak N30°E 39.71' (60d spike E									ŝ	77 E)	AvH3	rr. B	

Surroyer's Mishigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999

COLARD 30

2000

Date August 22, 2000