SURVEY & REMONUMENTATION'

DEC 13 2000

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

	corners in	Lo	cated in:	Corner Code	e#				~~	c	3 ;	:0
1.	Public Land Survey		T 18 W	R 9W	F-9					C C	-n. (TAIS:
			<u>T </u>	R						-	Ì	
			<u>T</u>	R								-353
	•		<u>T</u>	R					X8.800	: , (
2.	Property Controlling	s	Т	R						, ;	CO	}
	in Section	S	T	R		Registe	r of D)oode	Stam	n & F	ile Nı	ımher
	Property in Sec.	s	<u>T</u>	R	· 	Registe	1012	eeus	Stair	φαι	110 140	annoci
		s	_Τ	<u>R</u>				. n.		· ••		2 F B4
	ot No. Recorded Plat Private Claims					1 1						CL M
I. Robert L. Wetherell, in a field survey on May 16, 2000, do									1			
poi	hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and											
rules therefore as required in the current manual of survey instructions of the United 6 18 17 16 15 14 13 States Department of the Interior, Bureau of Land Management or by decree of a												
Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree 8												
Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							30	29	28	27	26	25
100	jovorou, rouria ao expre					12 13	31	32	33	34	35	36
F-9 - 1/4 Corner common to Sections 21 & 28, T18N, R9W												
Α.	A. Description of original monument and accessories and/or subsequent restoration:											

1978 - R.L. Wetherell, LS 24624 1838 - J. Hodgson, G.L.O. L.C.R.C. - Liber 02, Pg. 60. "Corner is a 14" Hemlock" Found Gun Barrel with Pine Stump Undated from Co. Surveyors Twp. Notes N70°E 4 feet. Replaced with Concrete Monument. Pages 5 & 59 #4 - 12" Maple West 55.76' "Gun Barrel" #5 - 8" Maple N44°W 57.51' #1 - 40" Pine N70°E 3 1/2 feet #6 - 4" Maple N6°W 20.95" #2 - 40" Pine N15°W 22 1/2 feet #7 - 6" Maple S42°E 53.74' #3 - Distance West = 2647.7°

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found the 4" x 36" Concrete Monument I placed in 1978.


Condition of the accessories are as follows: #1 Found stump, #2 Gone, #3 Measured 2642.5', #4 Found in good condition, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the 4" x 36" Concrete Monument as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

9" Tw. Maple S44°E 33.63' (60d spike E. side) #7
10" Maple N6°W 21.22' (60d spike N.W. side) #6
16" Maple N82°W 55.90' (60d spike N. side) #4
12" Maple N44°W 57.76' (60d spike N.E. side) #5
14" R. Oak S59°W 82.00' (60d spike N. side)

APPROVED LAND CORNER
P.A. 345 OF 1990
Osceola County
R.J.W
8-17-00



Signed by	Bobut	7.	Wetherell		Date August 22, 2000
Surveyor's M	ichigan License No. 246	524		5001110000	CONTRACTOR OF A TOTAL

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPLED FOR WORD PROCESSING JANUARY, 1999