FEB 1 2 1998

## LAND CORNER RECORDATION CERTIFICATE

SECTION	Filing Requiremen	t of Act 74, Mich. P.A. 1970	1
For corners in			·
Osceola (County)	Located In:	Corner Code #	APPROVED LAND CORNER P.A. 345 0F 1990 Osceola County
1. Public Land Survey	T 18N R 9W	J-13	6 Mars 1997
•			Markey M. Chang
	TR		
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	TRTRTRTRTRTR	Occupie of Michigan	Register of Deeds Stamp & File No
4. Lot No. , Recorde	nd Diet	Meceived For Record Mec. 26, 97 at 11:50 A.M.	авсрегоніјкьм
5. Private Claims  I, Craig W. McVean, in a field hereby state that under requirements o points mentioned in lines 1 and 2 above rules therefore as required in the currer States Department of the Interior, Bure Court of Law and /or that the corner poin conformance with the rules of the M Decree of a Court of Law; established, found as expressed below:	d survey on Oct. 28 f P.A. 74, Michigan P.A. of e were in conformance with nt manual of survey instruction au of Land Management or loints mentioned in lines 3, 4 lichigan Board of Land Surve re-established, monumented , all in the same town ar	NANCY CRAWFORD Register of Deeds  19 97 do 1970, the corner regulations and ons of the United by a decree of a and 5 above were eyors or by a d, recovered, and range, may be recorded on this	1
the South Twp. Bdy. No 6" Maple N70°E 30.4', E- DNR Survey Proj. # 75-4-	N57W 15 Lks., Maple ling - 1977 - FND. 1 1/4 US evidence. Set DNR N -W Random Due N 5.3', 4-K. J. Ostling - 1977	10" N49E 35 Lks	clude to be a Temple restoration of 'ost. 2" R. Oak N25°W 41.0',
B. Description of corner evidence	ce found and/or method	applied in restoring or reestablishi	ng corner:
accepted as the Standard monument represented J' It was also decided that S E & W for this is believed closing 1/4 corner at the	1/4 Corner. Upon Revie 1-T17N, R9W because H Standard 1/4 Corner show to be the method used turn of the century. Thu standard line through Tile	ew by Osceola Co. Remon Peer Glersey Twp. to the South is tiled build be re-established at the average by the remonumenting surveyor was we remove DNR Standard 1/4 (e. Mon. from East. Monument acc	e Monument along Township line and he roup it was decided that the Tile out Cedar Twp. to the North is not. Je closing Dist. per GLO 1/2 mile to the when established and monumenting the Corner Mon. from Tile location and Reset epted as a careful and faithful re-
C. Description of monument for c	orner and accessories es	stablished to perpetuate locating t	he position of the corner:
J-13 - 4" DNR A.C. on 1" x 36" 0.8' SE to Face. Set Blue N84°E 6.11' to N&T in N. N1°W 26.40' to N&T in W S28°W 52.61' to N&T in W East 34.32' to DNR Mon a J1-T17N, R9W (formerly u	Carsonite Post 1' N. Side 4" R. Maple scribed J. Side 6" R. Oak Scribed W. Side 12" R. Maple scat Tile being	d 'SCBT' d 'SCBT' ribed 'SCBT'	CRAIG W.  * McVEAN  PROFESSIONAL SURVEYOR No.