SURVEY & REMONUMENTATION

FEB 1 2 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich P A 1970

SECTION	Filing Requiremen	it of Act 74, Mich. P.A. 1970	1
For corners in			
Osceola (County)	Located In:	Corner Code #	APPROVED LAND CORNER P.A. 345 OF 1990
1. Public Land Survey	T 18N R 9W	<u>K-13</u>	Osceola County
	T R		Enflow (29)
•			Matthewall Elling
2. Property Controlling S	TR TR		
in Section S			Register of Deeds Stamp & File Num
3. Miscellaneous S Property in Sec. S	<u>T B</u> _		
Property in Sec. 3	1 N	OSCEOLA COUNTY	
4 lothic Boson		Sinte of Michigan	авсобесні ју им
4. Lot No, Record		1900 is at 1800 of 1900 of 1900 is at 1850 AM.	
		IANCY CRAWFORD	3
5. Private Claims		Eagloter Stilleons	4 7 8 9 10 11 12
			5
I, <u>Craig W. McVean</u> , in a fighereby state that under requirements			6 -18 -17 - 16 15 14 13 7
points mentioned in lines 1 and 2 aborules therefore as required in the curr	ve were in conformance with	regulations and	8 19 20 21 22 23 24
States Department of the Interior, Bu	reau of Land Management or I	by a decree of a	9
Court of Law and /or that the corner in conformance with the rules of the	•		10 30 29 20 27 25
Decree of a Court of Law; established found as expressed below:			11 31 32 33 34 35 36
·			13
NOTE: Not more than 2 corner certificate.	rs, all in the same town an	nd range, may be recorded on this	•
A Described of a data data.		16	
A. Description of original monu	iment and accessories and	d/or subsequent restoration:	
from East. Pine 12" I - LCRC L.2 P. 2 - K. J. C survey of the S. Twp. I N20°E 39.9', 3" Maple	N63E 37 Lks. Beech 9" N Ostling - 1977 - FND. Tile	Mon. which we conclude to be S e Mon. and cedar post. 5" Maple	37. Set wood post 80.00 chains tandard Corner as restored by Temple
B. Description of corner evider	nce found and/or method	applied in restoring or reestablish	ing corner:
should have been present Osceola Co. Remon. Per the South is tiled but Co closely 24.42' West of distance (24.42') West	nt along the Twp. line. He er Group it was decided the edar Twp. to the North is r Tile. Thus I remove Stand	e accepted the Tile Mon as the St nat the Tile Mon. was the closing not. 2. Probable GLO Pine Stp. I lard Cor. DNR Mon. from Tile loc ne through Tile Mon. Monument	tile monument where two monument tandard Corner. Upon review by the corner because; 1. Hersey Twp. to BT that fits Standard Corner Position ation and reset at record GLO closing accepted as a careful and faithful
C. Description of monument for	corner and accessories es	stablished to perpetuate locating	
N1°E 39.46′ to N&T in E N88°W 31.78′ to N&T ir S45°W 14.86′ to N&T ir		V. Pine Stp. (GLO) cribed 'SCBT' d 'SCBT' ed 'SCBT'	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088
Signed by <u>Craig W.</u>	mal		
Signed by <u>Croung W.</u> Surveyor's Michigan License No.	- I'M Vear	39088	Date 11/18/1997
		33000	_