NOV 1 6 1998

LAND CORNER RECORDATION CERTIFICATE

SECTION	Filing Requiremen	t of Act 74, Mich. P.A. 1970	
For corners in			
Osceola (County)	Located In:	Corner Code #	APPROVED LAND CORNER P.A. 345 OF 1990 Oscapla County
1. Public Land Survey	T 18N R 9W	M-3	Magatur M Georg
 Property Controlling in Section Miscellaneous Property in Sec. 	ST <u>/\$N_R_\$W</u>	<u>A-3</u>	Register of Deeds Stamp & File Num
4. Lot No , Re	corded Plat		Авсре г бніјкім
5. Private Claims			1 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12
hereby state that under requirements mentioned in lines 1 and 2 rules therefore as required in the States Department of the Interior Court of Law and /or that the coin conformance with the rules of	a field survey on April 7, nents of P.A. 74, Michigan P.A. of 2 above were in conformance with current manual of survey instructor, Bureau of Land Management or orner points mentioned in lines 3, 4 f the Michigan Board of Land Survey lished, re-established, monuments	i 1970, the corner In regulations and Itions of the United It by a decree of a It and 5 above were It work or by a	5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11
NOTE: Not more than 2 c certificate.	orners, all in the same town a	and range, may be recorded on this	12 31 32 33 3 3 3 3 3 3 3 3 3 3 3 3 3 3
A. Description of original r	nonument and accessories ar	nd/or subsequent restoration:	
Beech 12" Beech 7" GLO - Orson Lyon - 1 Beech 7" Beech 10" GLO Examination – A From 1891 to 1904 did the work. For the township. There Sometimes a solid til the work were kept i records.	e most part, a 3" glazed tile f were supposed to be 3 tile p e. with a cross in the top wa	rrect E. from standard post here & surveyed West. ty had a remonumentation program filled with cinders from a forge, wer per corner, placed atop of each othe s used, and sometimes a iron bar or pownships, and 5 of the townships h	, in which surveyors Temple and Trumbull, e placed at each government set corner in r, thereby making the corner 4 feet long. pipe was added to the tile. Notes of ave been entered in the County Surveyor's
		d applied in restoring or reestablishing	
Rod in 3" Vit. Tile I	er Common to Sec. 1 & 12, 1 Monument with cinders. And st available evidence of the p	cient fence corner for fence remains	R8W - FND. Bent 1/2" x 4' Long Iron S, E & W is 33' S. Monument
C. Description of monume	nt for corner and accessories	established to perpetuate locating t	he position of the corner:
Galv. Iron Pipe drove Reset 1/2" Iron Rod of Built Ring of Stone. N72°W 103.92' to N N32°W 23.53' to N& N23°E 25.55' to N& S37°E 27.26' to N&	ron Rod with 4" DNR Alum. Control center of tile Mon. on W. Side of tile as memorial Set Blue Carsonite Post 1' N. &T in S. Side 12" R. Pine scraft in NE Side 5" R. Maple scrift in SE Side 3" R. Maple scrift in SW Side 8" R. Oak scribert in W. Side 5" R. Oak scribert in W. Side 5" R. Oak scribert	il. Sibed 'XBT' OSCEOLA COUNTY Sibed 'XBT' REGISTER OF DEED Sibed 'XBT' 98 OCT 21 PM 4: 1	PROFESSIONAL SURVEYOR No. 39088
Signed by Osman	W. M. Va	·-	Date 10/14/1998
Surveyor's Michigan Licen:		39088	