NOV 1 6 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For cornession TION				
Osceola (County)	Located In:	Corner Code #		OVED LAND CORNER
1. Public Land Survey	T <u>18N</u> R <u>9W</u> T <i>/ያለ</i> J R <i>ያພ</i>	<u>/M7</u>	Mari	P.A. 345 OF 1990 Osceola County
2. Property Controlling S	TR		11400	3 July 981
in Section S	TR	EV-T-1		
3. Miscellaneous S Property in Sec. S	T R T R			
· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	Registe	r of Deeds Stamp & File Num
4. Lot No, Recorded	Plat			·
5. Private Claims			A B C D	E F G H I J K L M
1, Craig W. McVean, in a field survey on August, 19 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 5 6 - 18 - 17 - 16 - 15 - 14 - 13 - 7 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9	
NOTE: Not more than 2 corners, a certificate.	all in the same town and range, r	nay be recorded on this	10 30 29 11 12 31 32 13	28 27 26 25 33 34 35 36
A. Description of original monume	nt and accessories and/or subse	quent restoration:		
-GLO -Sub. T18N-R8W-Corre Lyon - 1847- Beech 12" N3: - From 1891 to 1904 approximat remonumentation program, in which Trumbull, did the work. For the mo- with cinders from a forge, were pla corner in the township. There was corner, placed atop of each other, t long. Sometimes a solid tile, with a sometimes a iron bar or pipe was a work were kept in ledgers, and give the townships have been entered in records.	Beech 18" N63°W 28L. ct E. from Standard Post- O. 3°E 9L., Beech 18" S62°E 38L. ely, Osceola County had a in surveyors Temple and est part, a 3" glazed tile filled ced at each government set supposed to be 3 tile per therby making the corner 4 feet a cross in the top was used, and dded to the tile. Notes of the en to the townships, and 5 of in the County Surveyor's found and/or method applied in c. 13 & 24, T18N-R9W & Sec. ron rod in vit. tile with DNR rence N-S. Cedar post rotted	-Osceola Co. Osc -LCRC- L. 2, P. 7- Mon. in N-S fenc cedar post - 4" R 18.0', 7" R. Oak	eola FB, P.26-27 K.J. Ostling-19 ce & 35' S of fer . Oak N 30°W 3 S10°E 34.4'	ist . to M6 & M8- 1904+ 7-Dist. E to B7-1905 77- Fnd. 1/2" iron in tile nce E. Add DNR Mon. & B1.8', 5" R. Oak N50°E 98 OCT 21 PH 4: 13
C. Description of monument for co	1"x 36" iron pipe with	to perpetuate locating th	ne position of the	o corner:
cap centered over in place 1/2" rod Reset cedar post on E. side. Set Ci S82°W 19.65' to set N&T in S side N36°W 32.05' to set N&T in E side N48°E 18.26' to set N&T in NW sid N84°E 56.10' to set N&T in S side S18°E 40.02' to set N&T in E side	arsonite post 1.5' N. 4' R. Maple scribed 'XBT' 8' R. Oak (KJO) de 10" R. Oak (KJO) Tri. 17" R. Maple scribed 'XBT'		TICE MED	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39068
Signed by Cruic, W.	M Year		Date/	0/14/1998
Surveyor's Michigan License No	39088			· ·