BURVEY & REMONUMENTATION

OCT 2 9 1996 LAND CORNER RECORDATION CERTIFICATE

CONTRACTOR Filing Requirement of Act 74, Mich. P.A. 1970

For corgerain COMMIS	SION				
(County)	Located In:	Corner Code ##			
(County)	18N 10	W L-5	l A	PPROVED LAND CORNER	
1. Public Land Survey	T R			P.A. 345 OF 1990	
	T R		- //	Osceola County	
	T R		- <i>I</i>	atthew Ill ISom	
	T R		- 2	6 Lent 1996	
	T R		-		
	T R T R		<u> </u>	of Boards Oliver of Etta Market	
	T R		— Register	of Deeds Stamp & File Number	
4. Lot No, Recorded			•••	всрегоніјкі	м
5. Private Claims]
			3		
Matthew McClung		September 20,	96 4	7 8 9 9 10 11 12	
I, , in a fi	eld survey on	, 19) , 5		_
do hereby certify that under requirement	its of P.A. 74, Michigan	P.A. of 1970, the corner point	smentioned 6	18 17 16 15 14 13	
in lines 1 and 2 above were in conformations of survey instructions of	~		_1		_
Management or by a decree of a Court o	f Law and/or that the co	orner points mentioned in lin	es 3, 4 and 5 8	19 20 21 22 23 24	
above were in conformance with the rul	es of the Michigan Boa	ard of Land Surveyors or by a	Decree of a		4
Court of Law; established, re-established expressed below:	shed, monumented,	re-monumented, recovered	n, round as	30 29 28 27 26 25	
NOTE: Not more than 4 corners,	all in the same tow	n and range, may be rec	orded 11		4
on this certificate.			12	_313233343536_	_
			13		┙
And Description of original monumers or lained corner	ent and accessories	and/or subsequent resto	oration:	10 7	
1838. Set wood post	40.00 chains	from South	oom noggso	n on 10 June	
Hemlock 10" N33W	6 lks.				
Sugar 9" S24E 27	lks.				
I have shown 3 LCRC; 371.	Liber 1, Pa	ige 381; Liber :	1, Page 394;	Liber 1, Page	
011.					
I have shown 5 PA 133 432, Page 219; Liber	326. Page 1	75. Tiber 205	Der 494, Page Dess 5/0	e 623; Liber	
, 2, -11, 12, 12, 12, 12, 12, 12, 12, 12, 12,	the, regular	.10, EIRCI 200,	rage 049.		
B. Description of corner evidence	found and/or meth	od applied in restoring or	reestablishing corn	er:	
Found axle shaft 1"	pelow road s	urface in North	1/2 of road	l to West, on	
curve of road to the Subdivision. L.C.R.	North. Cor	ner is South bo	oundary of re	oad for Knapp	
it state "Found brass	or ninet I	<pre>{age 381 is in</pre>	error under	Part B. where	
should State " Found	Axle Shaft"		OI, rage 354	under Sec. B	
				9 7	
				A S S S S	
				6 - 96	
	,				
	;	•			
				多 :	
C. Description of monument for c	orner and accessori	ice established to perpet	uate location the nos	/\ (3) €3~~	
Corner L-5. Osceola (onier and accessori	es established to perpet ent which is a	O' has some	yelon or ma comone	
1" pipe 18" in length	l.	cito, willen 18 d	. o brass ca	p mounted on a	
Telephone Pe	destal N76W	39.33 feet.		OF MICH	
1 1/2 Spruce		O feet.		194/2	
2" Spruce N1				TANATTHIN TO	1
N. Most Tree	in Clump of	f Basswood S34	W 36.12 f	eet A. McCLUNG	37
				* LAND *	15.50
				SURVEYOR &	X
				1202 /8	N.
	0			SURVEYOR S	ř
Just M	·collina		September 20	, 1996	
Signed by	13037	Da	te	The state of the s	
Surveyor's Michigan License No			FORM APPROVED BY	MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 15	
				REVISED MAY 14, 19 REVISED JAN., 19	