NOV 1 6 1998

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For	cornere	in	

Osceola (County)	Located In:	Corner Code #	
1. Public Land Survey	T_19N_R_9W	D-13	
2. Property Controlling	STR		
in Section 3. Miscellaneous	STR S T R		
Property in Sec.	S T R		

APPROVED LAND CORNER P.A. 345 OF 1990

Osceola County

Manuel Manuel

28 July 98

Register of Deeds Stamp & File Numb

4. Lot No	, Recorded Plat		···	
5. Private Claims _				
		•		

I, <u>Craig W. McVean</u>, in a field survey on <u>April 2</u>, <u>19 98</u>
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- D-13 GLO Set post J. Hodgson 1837 Beech 10" N23°W 15 L. Hemlock 9" N65°E 35 L.
  - Lyman W. June 1889 Stone at Govt. Cor.
     S 1/4 Sec. 32 Survey of Sec. 32, T19N, R9W
  - A.O. Temple 1892 Stone planted to perpetuate old corner. Set tile mon. Marks on Hem 9" N65°E 35 L. Maple 22" S29°W 278 L. Cherry 3" S78°E 207 L.
- Cedar F.B. P. 15 1904 Tile by stone

  Maple 4" N63 1/2° W 40'

  Maple 3" N11 1/2° E 21'

  Surroy of Sec. 5, T19N, B0W, -
- Survey of Sec. 5, T18N, R9W Rose Lake F.B. P. 29 1918 Tile by Stone Maple 4" N63 1/2°W 40'

Maple 3" N11 1/2°E 21' Survey Sec. 32, T19N, R9W REGISTER OF DEEDS

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- D-13 Standard 1/4 Corner common to Sec. 32, T19N, R9W. FND. 1/2" Iron Rod in brown 3" Dia. tile mon. with cinders in E-W gravel road., fences N & S. Stones around tile. Drove 4" DNR A.C. on 1" x 3' long iron pipe over 1/2" rod in tile. Built Ring of Stones with concrete. This monument is a original perpetuation of the S 1/4 cor. of Sec. 32 per June & Temple. Based on the closing corners 1/2 mile E & W there should be a closing 1/4 corner near this position. Based on the Cedar F.B. notes and occupation it is apparent that this tile monument has also been used as the N 1/4 of Sec. 5, T18N, R9W. Monument accepted as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner
- D-13 Drove 4" DNR A.C. on 1" x 3" long iron pipe over 1/2" iron rod in tile.

  Built Ring of Stone with concrete.

  N10°E 20.78' to Set N&T on E. Side 20" S. Maple (OBT).

  N64°W 39.19' to Set N&T on S. Side 20" S. Maple (OBT).

  N83°W 144.60' to Set N&T on S. Side 28" W. Pine.

  S53°E 67.19' to Set N&T on SW Side 16" twin S. Maple.

\$10°W 194.95' to NE cor. blk. foundation HSE. #16517.

Signed by Cruing W. Mk Ven 10/14/1998
Surveyor's Michigan License No. 39088

CRAIG W.
MCVFAN
PROFESSIONAL
SURVEYOR
No.
39088

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995