SURVEY & REMONUMENTATION

DEC 13 2000 LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

SECTION

	SECTION											
For corners in Osceola			Located in:	ocated in: Corner Code#						00) r	20 20 20
1.	Public Land Survey		T 20 N	R9W	E-2				,	 -	5 -	
			T	R					· .	-		ang. Nas
			<u>T</u>	R					را: ڈیکینا		<u></u>	SE
			Τ	R							ධ පි	開設が
2.			T	R					(``	وسي	
	in Section	s	T	<u>R</u>		Registe	rofΓ)eeds	Starr	າກ & F	ile Nu	umber
3.	Property in Sec.	s	<u>T</u>	R		rtogioto						
		s	<u>T</u>	_ R								
	Lot No. Recorded Plat					41	B	CDI	EFC	H	IJĸ	CL M
5.	•					2	6	5 🕈	4	3	2	1
I, Robert L. Wetherell, in a field survey on. June 5, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and							7	8	9	10	11	12
rui Sta	rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a						18	17	16	15	14	13
Co	ourt of Law and/or that th	ne corner	points mention	ned in lines 3,	4, and 5 above were	8	19	20	21	22	23	24

E-2 - 1/4 Corner common to Sections 4 & 5, T20N, R9W

recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree

Of a Court of Law; established, re-established, monumented, re-monumented,

1999-M. McClung, LS 13039 1891-1904-Temple/Trumbull/June 1838 - J. Hodgson, G.L.O. Remonumented T20N, R9W with Survey rec. L. 663, Pg 935. #1 - 10" Sugar N50°W 14 Links Found Tile & Iron. 3" Clay tiles with cinders. #2 - 16" Sugar S401/2°E 31 Links #7 - 24" Cherry S42°W 39.96' #8 - 16" Maple N34°W 51.62' Undated Co. Sur. Twp. Notes 1888 - L. June, Co. Sur. #9 - 14" Basswood S30°E 25.18' Tile & Iron #3 - Distance South 2636' #10 - 5" Maple N34°E 11.35' #4 - Distance North 4254.36 #3-Distance South = 2634' #4 - Distance South 4251' #5 - Elm N55°E 52.8'

#6 - 12" Maple S511/2°E 47'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a ½" rod inside a 3" Clay Tile. Corner is in a fence line North and South and 2.5 feet South of corner fence post for fence running west. It is in line with centerline old road bed to North.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Did not measure, #4 Did not measure, #5 Gone, #6 Gone, #7 Found in good condition, #8 Found in good condition, #10 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the ½" Rod with a 1" x 18" Pipe with Osceola County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

APPROVED LAND CORNER

Liber B Page

24" Cherry S42°W 39.96' (60d spike N.W. side) #7 16" Maple N34°W 51.62' (60d spike N.E. side) #8 14" Basswood S30°E 25.18' (60d spike S.W. side) #9 5" Maple Clump N34°E 11.35' (60d spike N.W. side) #10 P 345 OF 1990 Usceola County - 兄よい。 - 8-77-2000 ROBERT L.
WETHERELL
LAND
SURVEYOR
NO.
24624

25

26

35 36

igned by ___

Robert & Wetherell

Date August 22, 2000

9

28

33

27

34

10 30 29

11

12

31

32

Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975

657