LAND CORNER RECORDATION CERTIFICATE

Liber 4 pg. 64 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code # Oscoda Located in: STATE OF MICHIGAN OSCODA COUNTY T 26N R 2E 1. Public Land Survey FILED Т R Т R 2 AUG 95 9:36 A.M. _ R Т 2. Property Controlling PATSY J. PETERS _ R ___T __ in Section S REGISTER OF DEEDS Т_ S R 3. Miscellaneous Register of Deeds Stamp & File Number _ R _ Property in Section S T _, Recorded Plat 4. Lot No. 5. Private Claims __ June 5 , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: L.2 of plat, pg.21 G.D. Henning Sept. 23, 1960 Mon-US GLO Bronze Cap in 3/4" Pipe LCRC L.3, pg. 258 G. Wilson Sept. 21, 1992 GLO-L. Clawson May 1839 Mon-Post Mon-Fd. GLO Mon. raised with 6" WIT: 5" Spruce S69½°W 35 1ks. 9" Spruce N62°W 67 1ks. 10" Aspen 534°E 20 1ks. in road
WIT: 14" B.Oak S42°W 91.60'
18" B.Oak N73°W 41.00'
SW Cor. Bldg. S52°E 71.00' Iron & Cap WIT: 16" R.Pine N59°E 117.14' 5" R.Pine N51°W 82.93' 8" Aspen N42°E 19 1ks. SW Cor. of Foundation 852°E 69.98' John Randall Dec. 27, 1887 L. 2, pg.77 N. Caldwell Apr. 22, 1969 MOn-Fd. US GLO Mon. WIT: SW Cor. Bldg. S52°E 71.00' 18" Oak N79°W 41.90' Mon-Unknown 16" B.Oak S72°W 160.81' WIT: 8" Spruce S83°W 1.85 chs. L.193, pg.7518 L. Beauregard Oct. 1993 Gedar cor. fence post N39°W 89 chs. Oct. 1993 Mon-Fd. ½" Bar & Cap WIT: 18" Norway N59°E 117.14' 20" Tw. Oak N85°W 40.85' 4" Norway N51°W 82.91' 15" Oak S72°W 160.81' GLO-G. Veal Oc. 1935 Telephone Pole N44°E 47.001 Mon-Intersection of roads accepted as L.1, pg.116 N. Caldwell Sept. 15, 1971 Mon-Unknown WIT: S89°14'50"W 2480.30' ½ Cor. best availabe evidence; Set Conc. Mon. with Brass Tablet
WIT: 10" J.Pine N60½°E 70 lks.
14" B.Oak N78 3/4°W 61½ lks.
6" J.Pine S44°E 110½ lks. N00°07'10"E 2634.00' % Cor. N. Caldwell files L.1, pg.205 N. Caldwell July 7, 1972 Mon-Unknown WIT: PK Nail 889°14'50'W 734.25' 7" J.Pine S36%°W 104 1ks. Possible Lucas Wit. Possible Lucas Wit.

Mon-Fd. GLO

WIT: 1" pipe 33' North

1" pipe 33' West

1" pipe 33' East

SW Bldg. Cor. S52°E 70.98'

18" Oak N79°W 41.89'

T.Pole N44°E 46.97'

14" Oak S42°W 81.60' L.1 of plats, pg.25 G. Henning Mar. 1940 Mon-Unknown PK Nail N00°07'10"E 396.00' WIT: None given pg.487 N. Caldwell Mar. 27, 1974 MSHID MKW 1958 Mon-Unknown Mon-Brass Cap WIT: Nail S89°14'50"W 278.00' WIT: 18" Oak N79°W 41.89 Nail N00°07'10"E 396.00' Telephone pole N44°E 46.97' SW Cor. Bldg. S52°E 70.98' 14" Oak S42°W 91.60 Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found ½" Bar & Cap. Found USGLO concrete monument under ½"x4" bar & cap. Accepted as the best available evidence of the re-establishment of the Original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: STATE OF MI USGLO concrete monument. Mon-WIT: Fd. 18" Norway N59°E 117.14'
Fd. 20" Tw. Oaks N85°W 41.85' (recorded as 40.85')
Fd. 4" Norway N51°W 82.91'
Fd. 15" Oak S72°W 160.80' STATE OF MICHIGA **APPROVED** 合 MARVIN E. County Remonumentation MYERS PROFESSIONAL Peer Review Group SURVEYOR 3/20695 35.0 31660 UFESSION A

31600

Surveyor's Michigan License No.

REVISED MAY 14, 1975

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971