Liber 4 Pq. 98

STATE OF HICHIGAN
OSCODA COUNTY
FILED

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

19 SEP 95 4:03 P.H.

For corners in	rung Requirem	70 17 OEF 90 4:03 P.M.	
Oscoda (County)	Located In:	Corner Code #	PATSY J. PETERS REGISTER OF DEEDS
Public Land Survey	T <u>26 N R 2 E</u> T R T R T R	F-13	
2. Property Controlling in Section	ST R ST R		•
3 . Miscellaneous Property in Section	ST R ST R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		

I, Larry G. Beauregard, in a field survey on March 13, , 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

5. Private Claims

A. Description of original monument and accessories and/or subsequent restoration:

8-8-1838, Lewis Clason, Deputy Surveyor, set ‡ Section post. Witnesses marked: (N 48° E 31 links 10" Hemlock) (N 74° W 16 links 10" Hemlock).

9-28-1914, C.O. Seeley, Deputy Surveyor, set ‡ corner post. No witnesses marked.

1924, Guy R. Veal, Dependent Resurvey, set iron post, 3' long, 1" diam., 42" in ground, for reestablished & Section corne of Section 33. No bearing trees available, pits impracticable.

3-17-1973, Norman C. Caldwell, P.S. #12018, found Rec. $1\frac{1}{2}$ " pipe in pavement, West 18.0' North $\frac{1}{4}$ corner Section 4, T 25 N R 2 E. Boundary survey Recorded L. 1, P. 291, Oscoda County Records.

11-11-1994, Larry G. Beauregard, P.S. #18654, found 2" pipe in pavement, 17.83' East of N. ‡ corner for Section 4, T 25 N R 2 E. Boundary survey. No references marked.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Existing 2" pipe & cap set by Norman Caldwell in 1966. No references marked.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1 corner for Section 33, T 26 N, R 2 E

\$ 05° E 89.75' 8" Ash

Oscoda County Remonumentation cap P.S. #18654 on a 5/8" x 18" bar inside a 2" x 12" pipe, this all being inside a monumen box. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on July 14, 1995.

North	35.63'	Corner fence post	-	Placed	P.K.	nail	&	P.5	tag	#18654	ļ
N 70° W	113.451	Telephone Pole	-	Placed	P.K.	nail	8.	P.S.	tag	#18654	ļ
S 30° E	52.621	8" Boxelder	-	Placed	30 p	enny	spi	ike &	P.S.	tag /	/1865

APPROVED

County Remonumentation
Peer Review Group

. 0 5	1		alalar
Signed by Fann Day	Besirand	Date	7/8/95
// /			,, , , ,
Surveyor's Michigan License No	18654	FORM APPROVED BY MICHIGAN	STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
•			REVISED MAY 14, 1975
			REVISED JAN., 1983

- Placed 30 penny spike & P.S. tag #18654