SUNVEY & REMONUMENTATION

OCT 0 8 1997 Filing Requirement of Act 74 Mich DA 4000 Liber 4 Rage 173 COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Oscoda Located In: Corner Code # (County) STATE OF MICHIGAN DSCODA COUNTY 1. Public Land Survey T27N R 3E FILED B-11 29 AUG 97 9:00 A.M. 2. Property Controlling PATSY J. PETERS in Section 3. Miscellaneous REGISTER OF DEEDS Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. _ , Recorded Plat 5. Private Claims I. Marvin E. Myers, P.S., in a field survey on __June 25 ____, 19.97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the current manual of survey instructions of the Michigan. that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 5 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 6 7 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 8 10 Description of original monument and accessories and/or subsequent restoration: GLO - Oct 17,1839 L. Clason, D.S. County Surveyor's records (No name or date) Mon - Post Mon - Found Seeley's iron stake Wit: 10" Birch S17°E 42 Lks Wit: Found Seeley's Concrete monument, found bearing to be N36°E mag var. 2½°E 8" Aspen N20°W 12 Llks (This may be G. F. Delamater's work see page 192 and 194 of book1) Sept 26, 1888 J. Randall, Co. Surveyor LCRC L. 1, P. 224 N. Caldwell, P.S. #12018 Jan, 30, 1979 Mon: Found 1/2" bar & cap over 2" pipe Mon- Set Post single proportion. Wit. 30" W. Pine Stump West 31/2 Lks Wit: 10" Apple N21°E 97.0 Sept 19, 1916 C. O. Seeley, Co. Surveyor 6" Tw. Cedar \$18°W 66.3 Mon - Found Randall stake with brick set 5" Cedar South 59.5 **APPROVED** 2" Iron tubing at 1/4 post. 1/2" bar & cap North 33,00 Wit: Cement Monument witness N33°E 421/4 Lks. County Remonumentation Description of corner evidence found and/or method applied in restoring or reestablishing corner: NCC/IZ AUG 97 Peer Review Group Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 12" long cabin spike in monument box; with the following accessories: Found nail in E. Side 7" Norway NO2"W 74.60; found nail & tag #18654 N.29°E 97.0; found 8" Cedar stump South 59.5 to face; found cement witness monument removed Standard Oscoda County Cap C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Mon- Set Standard Oscoda County Monument in existing Monument box in centerline of E-W paved road. Spike in West side of 3" Cedar S46°W 42.78 Spike in East side of Cedar fence post N11°E 36.90 Spike in face of 6" Poplar N53°W 65.17

OFESSION **SURVEYOR** 21600 OCESSION N

Surveyor's Michigan License No.

MYERS