

NOV 0 3 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION	,g	•	
Oscoda	Located In:	Corner Code #	Liber 4 Pg 26
(County)	Comins Twp.		STATE OF MICHIGAN
1. Public Land Survey	T <u>27N</u> R <u>3</u> TR TR		OSCODA COUNTY FILED
Property Controlling in Section	S TR S S		27 AUG 98 9:52 A.M. PATSY J. PETERS
3. Miscellaneous	TR S TR		REGISTER OF DEEDS Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No, Rec	orded Plat		ABCDEFGHIJKL
5. Private Claims			
			3
			4 7 8 9 10 11 12
		eld survey on <u>April</u> , 199 n P.A. of 1970, the comer points men	
in lines 1 and 2 above were in	conformance with regulation	ons and rules therefore as required	in the 7
Management or by a decree of a	Court of Law and /or that th	Department of the Interior, Bureau on the comer points mentioned in lines 3,	4 and
		Board of Land Surveyors or by a Dec covered, found as expressed below:	cree of 10 - 30 - 29 - 28 - 27 - 26 - 25 -
NOTE: Not more than 2 corr	ners, all in the same town	and range, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
		MP	PROVED
		County	Remonumentation 3 AUG 98 Review Grown
A. Description of original	monument and accesso	Peer pries and/or subsequent restora	Review Group
F-5 comer common for Sec			p
Oct. 1839 - W.R.Coon D.S.	set quarter section post.	Wit's mkd. (10"cedar N37E 6lks)(8"c	cedar S37W 9lks)
Apr. 1971 - Norman C. Ca Henning R.I.S. Filed Com	idwell RLS #12018 - Set cap er Registry bk #2, page 359	o and pipe. Comer was determined Wit's mkd. North. 33' (1/2" bar) E	by single proportion between Section Comers set by ast 58.28' (N1/4 cor. Sec.16.)
Henning, R.L.S. Filed Comer Registry bk #2, page 359. Wit's mkd. North. 33' (1/2" bar) East 58.28' (N1/4 cor. Sec.16.) May 1971 - Norman C. Caldwell RLS#12018 - Fnd. Oscoda Co. Std. Cor. (No wit's mkd.) Filed Act #132 Rec. L.1, Pgs. 76, 77, 78, & 79. Sept. 1979 - Norman C. Caldwell RLS #12018 - Set 1/2" bar & cap by S.P. in centerline Helmer Lake Rd. Wit's mkd. (East 59.5 Fence South)			
(North 33.0' 1/2" bar and ca	ap.)(East 58.53' 1/2" bar & c	ap)(N. 1/4 Cor. Sec. 16) Survey Re	c. L.3, Pgs. 127 & 138.
B. Description of corner	evidence found and/or r	nethod applied in restoring or	reestablishing corner:
April 1998 - Fnd. 1/2* bar &	cap in Mon. Box c/l Helmer	Lake Rd. Replaced with 5/8" x 18" b	ar & Oscoda Co, re-mon cap.
(East 58.50' (M) Fnd.Proper	ty controlling comer for sect	ion 16. Replaced with 5/8" x 18" bar	& Oscoda Co. Re-mon cap. Mkd PCC for Sec. 16. well on Aug. 23, 1961. Oscoda Co. Records. It has been
determined that the proper			t in the wrong location due to a computing error along
the Section line. C. Description of monum	ont for corner and acce	sentiae actablished to perpetu	ate locating the position of the corner:
•			
F-5 comer for Section 9 &			*
2" aluminum Re-mon. cap Approved by the peer grou		box. Accepted as a careful and failt	aful establishment of the position of the corner.
S30E P.Pole S10E 10"W.Pine		ed Pk nail & PS tag #18654 ed 60d spike & PS tag 18654)	No.
S15W 6'Norway Pine N50W 1/2'Bar & cap #1	151.36 (Place	d 60d spike & PS tag 19654	
East	58.50 5/8 Re	ebar w/Remon cap (P.C.C. Sec. 16)	g a. 00
Signed by	D. Bewegard	, 	Date 7-31-98
Surveyor's Michigan License No	. 18654		SURVEYORS, JAN 28, 1971 REVISED MANUAL TO SURVEYORS AND
			SURVETORS, JAIN 20, 1971 REVISED MARINA, 1975

LARRY G. BEAUREGAFD

No.