## SURVEY & REMONUMENTATION.

OCT 0 8 1997

Surveyor's Michigan License No.

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Liber	4	Pagé	177
	•	/	•

For corners in	7 11119 1100	un oment of Aut 74, inc	
Oscoda (County)	Located In:	Corner Code #	STATE OF NICHIGAN OSCODA COUNTY FILED
1. Public Land Survey	T27N R <u>3E</u> T R T R	F-11	29 AUG 97 9:04 A.M. PATSY J. PETERS
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	TR TR TR TR		REGISTER OF DEEDS  Register of Deeds Stamp & File Number
4. Lot No, Recorded F 5. Private Claims	Plat		A B C D E F G H I J K L  2 6 5 4 3 2
I, Marvin E. Myers, P.S., in a field s of P.A. 74, Michigan P.A. of 1970, the with regulations and rules therefore as States Department of the Interior, Burea the corner points mentioned in lines 3, 4 of Land Surveyors or by a Decree of a found as expressed below:	corner points mentioned in required in the current may au of Land Management or and 5 above were in confor Court of Law; established	lines 1 and 2 above were in co anual of survey instructions of by a decree of a Court of Law a mance with the rules of the Mich , re-established, monumented,	quirements 4 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 2 corners, at on this certificate.	I in the same town and r	ange, may be recorded -	9 10 30 29 28 27 26 2 11 12 31 32 33 34 35 3
A. Description of original monumer GLO - Oct 1839 L. Clason Mon - Post     Wit: 8" Aspen N47°E 9 Lks	L3, P 100 ( Mon - Place Wit: 8" R. F	or subsequent restoration: Caldwell, P.S. #12018 July 2 d Standard County Corner Pine S50°E 20.3 Pine S20°W 9.3	
14" Birch S48°W 20 Lks	3" R. P	ine N70°E 33.3 corner North 0.5	APPROVED  County Remonumentation
LCRC L. 1, P. 228 N, Caldwell, P.S 18" W. Pine S20°W 9.3 3" R. Pine N70°E 33.3 Fence corner North 0.5	. #12018 Sept 27, 1979		NCC/12 AUG 97
<ul> <li>Description of corner evidence Found Standard Oscoda County Mo in face of 27" W. Pine S28°W 8.98;</li> </ul>	nument; found the following	accessories, 8" R. Pine stump	olishing corner: • S50°E 20.3; found blaze in face 6" R. Pine N54°E 33.3; found bla inful establishment of the Position of the Corner.
C. Description of monument for co % common to Sections 28, & 33, T2 Mon - Standard Oscoda Cou Wit: Nail in SE side 27" W. P Nail in E. side 22" W. Pir Nail in SE side 6" R. Pine Nail in NE side 4" Spruce Fence post North 0.5	17N, R3E U <b>nty Monument</b> Ine S28°W 9.90 ne N06°W 34.80 e N54°E 20.45	tablished to perpetuate loca	Ating the position of the corner:  ARRYIN E.  MYERS PROFESSIONAL SURVEYOR NO. 31600 S1600
			OFESSIONAL MANAGEMENT OF THE PROPERTY OF THE P