LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in	Filing Requirer	ment of Act 74, Mich. P.A. 1	1970 Liber 4 Pg 27=
			,
Oscoda (County)	Located In: Comins Twp.	Corner Code #	STATE OF MICHIGAN OSCODA COUNTY FILED
1. Public Land Survey	T <u>27N</u> R <u>3 E</u> T R T R	l-2	27 AUG 98 10:03 A.M.
2. Property Controlling S_ in Section S_	T R T R		PATSY J. PETERS REGISTER OF DEEDS
3. Miscellaneous S_T			Register of Deeds Stamp & File Numbe
Property in Sec. S_ T_	R		
4. Lot No, Recorde	d Plat	PROVED	ABCDEFGHIJKL
5. Private Claims	21/A	Remonumentation	2 6 5 4 3 2 1
	Peer	Review Group	3
\//	AUG	aroup	4 - 7 - 8 - 9 - 10 - 11 - 12
I, Larry G. Beauregard	′ íoa field sun.	rey on April, 1998	5
do hereby state that under requirement	ts of P.A. 74, Michigan P.A. of	1970, the comer points mentioned	6 18 17 16 15 14 13
in lines 1 and 2 above were in confo current manual of survey instructions	of the United States Departme	ent of the Interior, Bureau of Land	7 8 19 20 21 22 23 24
Management or by a decree of a Court 5 above were in conformance with the	t of Law and /or that the come:	r points mentioned in lines 3, 4 and	8 19 20 21 22 23 24
a Court of Law; established, re-established	hed, monumented, recovered,	found as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 2 corners. a	ill in the same town and rang	ne may he recorded	11
on this certificate.	III die danie totti die raig	go, may be recorded	12 31 32 34 35 36
A. Description of original monu	ment and accessories an	id/or subsequent restoration:	13
I-2 Comer for Section 2 & 3 T27		, , ,	
			•
July 1885 - John Randall, Co, Su Aug. 1978 Norman C. Caldwell R' Sept 1989 - Clifford C. Lindgren F (N85W 47.79'P.Pole(N30W 48.17' 1996 - MDOT plans - project DST Dec. 1997 - Daniel E. Schripsema	rveyor - Set 1/4 post on correct LS#12018 - Set 1" Bar & mon, RLS#14098 - Fnd. 5/8" rod in n "Mail Box Post)(N25E 62.50'T. P9668(001) - Control Section a RLS#24617 - Fnd 5/8" rod in	non. box. 1'E of M-33 C/L. Prev. Re RiserPole)(N50E 78.72'P.Pole). 68012. const. sheet no. 33.	V 56lks)(10"Hemiock S55W 53lks) Vest 47.3'P.Pole)Survey Rec.L.2, Pgs. 637 & 638. ec. in L.1, P.210, 1978. Wit;s
B. Description of corner evider	ice found and/or method	applied in restoring or reestab	lishing corner:
April 1998 - Fnd. 1/2" x 18" bar 8 Re-mon cap.	& P.S. cap #24617 in Monu. bo	ox 2 ± East of M-33 C/L. Wit"s by	Schripsema. Re-placed with 5/8" x 18" bar &
C. Description of monument for	r corner and accessories	established to perpetuate loca	ating the position of the corner:
I-2 Corner Common for Section 2	& 3 T27N, R3E.		
2" aluminum Re-mon cap on 5/8" x Approved by the Peer Group on Ju	t 18" bar in Mon. box. Accept ly 10, 1998.	ed as the best available evidence of	the position of the original comer.
East 59.10 (Ex. 1/2*Pipe N16W 115.63' (x) W.end of cr	N16E 116.4 mp.) N64W 53.8		#18654.)
Signed by	De Beaux	gaid Date	7-31-98
Surveyor's Michigan License No. 186	54		D BY MICHIGAN STATR BOARD OF PROFESSIONAL
CUDVEV 8			EYORS, JAN 28, 1971 REVISION MAN 1983 REVISION MAN 1983

SURVEY & REMONUMENTATION

NOV 0 3 1998

SECTION

