LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•		Liber 4	pg. 81
Oscoda	Located In:	Corner Code ##	Liber	1 1. 0 1
Public Land Survey	т <u>27N</u> R <u>4E</u> т R	1– 6	STATE OF MIC OSCODA COL FILEI	INTY
	T R	· ·	2 AUG 95 9	42 A M
in Section S 3. Miscellaneous S	T R T R T R T R		PATSY J. P Register of Deeds Stamp & Fi	ETERS
4. Lot No, Recorded	l Plat		—— АВС D E F G I	HIJKLW
1. David B. Babbitt in a field of hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-establishers expressed below: NOTE: Not more than 4 corners, a on this certificate.	Id survey on sof P.A. 74, Michigan P.A. clance with regulations and the United States Departr Law and/or that the corner is of the Michigan Board of shed, monumented, re-mall in the same town and	July , 19 94 of 1970, the corner points mentioned is rules therefore as required in the ment of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a conumented, recovered, found as displaying the manage, may be recorded	2 6 5 4 3 3 4 7 8 9 11 5 6 18 17 16 1	D
I-6; Thomas Pattison, 18 BTs; Y. Pine 10 - N C. O. Seeley, May, NBT; Y. Pine Stp	340, Set wood post 32E - 16 Lks., Sp 1912, "Set 14 betw N88W - 02 Lks.	t pr. Pine 4 - S42W - 21 ween sections 14 & 15.	Lks. "No description of Months that this corner was	
B. Description of corner evidence I searched this area but The section corner commo 10 & 11 both fall in Sha was extended across the or West between sections the section corner commo 14-15-22 & 23. Traces of which agrees with Seeley not state his method of indicate any method other and faithful reestablish	found no evidence on to sections 10- mrock Lake. The lake by trigonome 10 & 15. Therefore to sections 2- cold road bed are 1912 highway a reestablishing the trian single pro-	ce of any previous cor: -11-14 & 15 and the 14- 1840 G.L.O. notes indi- etry with no direct ti- or, this corner was se- 3-10 & 11 and the sect- e discernable North an- survey notes. C. O. Se- nis corner but there in oportion. This position	ner monument or access corner common to secticate that the original es East between section to by single proportion ion corner common to s d Southwest from this eley's 1912 survey not s nothing in his notes in is accepted as a car-	ons survey ns 11 & 14 between ections point es do to
C. Description of manument for co	orner and accessories e	stablished to perpetuate locating	ng the position of the corner:	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-6; Set 1" pipe with Oscoda County brass cap 11" Oak - N84E- 6.70' 21" N. Pine - S43W - 104.25' 22" Oak - N25W - 25.69' 20" Oak - N11E - 67.39' County Remonumentation Peer Review Group 31#### 95				
All bearings are actual each witness tree at the			to a 3" nail in the si	de of
Signed by Lavis B	Bolditt	Date Sep	t. 26, 1994	
Surveyor's Michigan License No. 21558 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197! REVISED JAN., 198:				
			**************************************	Andrew Contraction of the