OTSEGO COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

JN EICATE	LIBER	00	0 1	PAULU	9	5
--------------	-------	----	-----	-------	---	---

1. Public Land Survey 1. I. R. B. L. B. L. B.	For	corners in		ent of Act 74, Mich. P.A. act 345, PA 1990	1113000 000 11	Y	•
1. Public Land Survey 1. 11.1.8 P. 1.K. 9-12 1. Property Controlling 2. Property Controlling 3. 1 P. R. 1		OTSEGO			RECEIVED FOR RE	CORD	
Property Controlling S	1.						
in Section S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Recorded Plat Recorded Recor		O A. Cambaallina	T R T R		CLERK/REGISTER OF	DEEDS	
4. Lot No		in Section Miscellaneous	S T R S T R		Register of Deeds Sta	mp & File Numi	ber
5. Private Claims 1. Carl I. Robinson in a field survey on September 13, 19 95 de heroby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the fundes distance begaring the the factors of the fundes distance of the fundes							
do hereby cettify that under requirements of PA. 74. Michigan PA. of 1970, the corner periods mentioned in lines 1 and 2 above were in conformance with requisitions and regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Count of Lawa Gourd Lawa and Management or by a decree of a Count of Lawa Count of Lawa Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of the interior, Bureau of Land Management of a continued on the count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of the interior, Bureau of Lawa Management of the interior, Bureau of Lawa (Lawa Management of Management of the Interior) and the county of the County Management of the Interior of the County Management of the Interior of Lawa (Lawa Management of Management of Management of Management of the Interior of Lawa (Lawa Management of Manag					A B C D E	F G H I J	K L
do hereby certify that under requirements of PA. 74. Michigan PA. of 1970, the corner points menioned in lines 1 and 2 above were in conformance with requisitions and regulation and relies therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Count of Lawa, destablished, except in the three points menioned interest. A and 5 above were in conformance with interiors under the conformance with required of Land Surveyors of by a Decree of a Count of Lawa, established, exceptablished, monomented, re-anomalized conformanced. The County of Lawa, established, exceptablished, monomented, re-anomalized conformanced and the conformance of the conformance on this certificate. A. Description of original monument and accessories and/or subsequent restoration. Q.O. 2/777: Fust.th Brut, 1850: Set Qr. Sec. Fost-Beech 8" East 33 lks (22.0"), Sugar 8" S 64" 29 lks (19.3"). CSR 2/322: G.F. DeLawater, 1921: 2" Concrete with (11)egibly?) center 20" E & M., corner is exactly in center of payement-Line 4" S 79" 68.2", Elm 6" N 89" 68.4", 68 Pipe East 2.55" & Next 2.55" &					2 - 6 - 5 5 3	4-1-3-1-2-	<u> </u>
do hereby cettify that under requirements of PA. 74. Michigan PA. of 1970, the corner periods mentioned in lines 1 and 2 above were in conformance with requisitions and regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Count of Lawa Gourd Lawa and Management or by a decree of a Count of Lawa Count of Lawa Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of the interior, Bureau of Land Management of a continued on the count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of by a decree of a Count of Lawa (Lawa Management of the interior, Bureau of Lawa Management of the interior, Bureau of Lawa (Lawa Management of Management of the Interior) and the county of the County Management of the Interior of the County Management of the Interior of Lawa (Lawa Management of Management of Management of Management of the Interior of Lawa (Lawa Management of Manag					4-7-4-8-1-	9	
in lines 1 and 2 above were in conformance with regulations and rules therefore as recurred in the current manual of survey instructions of the United States Department of the Interior, Survey to Date and Management or by a decree of a Court of Law and/or lind the corner points mentioned in lines 3.4 and 5 above were in conformance with interities to the conformance with the regular bloom of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. CLG 2/277: Mustin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). CCR 2/272: Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks (22.0°), Sugar 8° 5 64°M 29 1ks (19.3°). Suptin Burt, 1850: Set Dr. Sec. Post-Beech 8° East 33 1ks	I	Carl I. Robinson	, in a field survey on Se	ptember 13, 19 93	- 5	┦═ ╂═╁ ┈╏ ═╬	+
Current manual of syst decree of a Count of Laward/or histothe corresponds surveyors and state of the Management of the Account of Laward/or histothe corresponds surveyors or by a Decree of a cover were in conformance with me included of the Michigan board of Land Surveyors or by a Decree of a cover of Laward or substituted residualished, monountmented, re-monountmented recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. GLO 2/777: Austin Burt, 1850: Set Qr. Sec. Post-Beech 8" East 33 lks (22.0"), Sugar 8" S 64°% 29 lks (19.3"). CSR 2/322: 6.F. DetaMater, 1921: 2" Concrete with (Illegibly?) center 20" £ & W. corner is exactly in center of payement-Late 4" S 8"ye a 8.4", E lan 6" N 89" & 6.4", C sas Pipe East 23.2" & West 24.25". CSR 2/318: 6.F. DetaMater, 1936: Copper Lack in 2" Square Coder plug in Concrete Payement. LCR 1/47: W.W. Macerbut, 1972: Found 1" Iron 0.3" down, spk T & P. Pole N 90°E 31.6", spk P. Pole N 35°W 30.51". Misc.: C.I. Robinson, 1989: Removed Obsego County Nonument while constructing 30" Storm Sewer crossing. Set PK nall in centering of Payement Nant 33.1", Nakachut's witnesses unfailsturbed. Set PK nall in center in 1990 because N. Center Street was proposed for reconstruction. This was reasowed in 1994 during construction and not replaced. B. Description of corner evidence bound and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monament in corner is accepted as a careful and faithful reestablishing corner. Replaced Otsego County Monament in corner is accepted as a careful and faithful reestablishing corner. Replaced Otsego County Monament in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01", 3" iron rod N 85°E 33.00", spk P.Pole S 15°E 87.13", spk P. Pole N 40°W 37.97". QISEGO County Monament in C	in li	nes 1 and 2 above were in	n conformance with regulations and re	ules therefore as required in the	he i	16-1-15-1-14-	13-
above were in conformance with the rules of the Michigan board of Land Surveyors or by a Decree of a Count of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. CLO 2/277: Austin Burt, 1850: Set Or. Sec. Post-Beech 8" East 33 lbs (22.0"), Sugar 8" 5 64"W 29 lbs (19.3"). CSR 2/325: G.F. DelaMater, 1921: Concrete with (Hilegibly) center 20" E & W, corner is exactly in center of pavement-Ela 4" S 87"E 48.2", Ela 6" N 85"W 64.4", Gas Pipe East 25.25" & West 24.95". CSR 2/318: G.F. DelaMater, 1936: Copper Lack in 2" Source Code plug in Concrete Pavement. LCR 1/47: W.W. Wakerhut, 1972: Found 1" Iron 0.3" down, apk T & P. Pole N 50"E 31.86", spk P.Pole N 35"W 30.51". Misc.: C.I. Robinson, 1989: Removed Obsego County Monument while constructing 30" Storm Sewer crossing. Set PK nail in center line of Pavement North 33. 13", Wakenhut's witnesses undisturbed. Set PK nail in corner in 1990 because N. Center Street was proposed for reconstruction. This was removed in 1994 during construction and not replaced. B. Description of corner evidence bound and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monument in corner from Wakenhut's T & P Pole N 6.2" iron rod east 33.0 (Cert. of Survey, L. 416, P.359) and measurements north & south to G-11 & G-13, respectively, proportioned to previous measurements on file in my office. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Spike in P. Pole N 60"E 32.01", ½" iron rod 85°E 33.00", spk P.Pole S 15°E 87.13", spk P. Pole N 40"W 37.97". C. Description of monument for corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60"E 32.01", ½" iron rod 85°E 33.00", spk P.Pole S 15°E 87.13", s	Mar	ragement or by a decree of a	a Court of Law and/or that the corner po	oints mentioned in lines 3, 4 and	15 8 19 20	212223-	24-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. CLO 2/277: Austin Burt, 1850: Set Or. Sec. Post-Beech 8" East 3) 1ks (22.0"), Sugar 8" S 64°W 29 1ks (19.3"). CSR 2/325: G.F. DelaMater, 1951: Concrete with (Illegibly) center 20" is & W, corner is exactly in center of payment-Eln 4" S 87°E 48.2", £in 6" N 85°W 64.4", Gas Pipe East 25:25" & West 24:95". CSR 2/318: G.F. DelaMater, 1951: Copper tack in 2" Square todar plugi in Connectee Payment. LCR 1/47: W.W. Waxerhut, 1972: Found ½" Iron 0.3" down, spk T & P. Pole N 50°E 31.66", spk P. Pole N 35°W 30.51". Misc.: C.I. Robinson, 1969: Femoved Obsept County Monument while constructing 30" Storn Sewer crossing. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment North 33, 13", Wakerhut's witnesses undisturbed. Set PK nail in center line of Payment in corner in 1590 because N. Center Street was proposed for reconstruction. This was resounded in 1994 during construction and not replaced. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monument in corner from Wakenhut's T & P Pole NE, ½" iron rod east 33.0 (Cert. of Survey, L. 416, P. 359) and measurements north & south to G-11 & G-13, respectively, proportioned to previous measurements on file in my office. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Approved by the County Survey Poor Group. December 10, 1995. CARLL M	abo	ve were in conformance wit	th the rules of the Michigan Board of La	and Surveyors or by a Decree o	ta allill	┧╌╂╌╂╌╂	
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Q.O. 2/777: Austin Burt, 1850: Set Qr. Sec. Post-Beech 8" East 33 1ks (22.0"), Sugar 8" 5 64"M 29 1ks (19.3"). CSR 2/322: G.F. DeLaMater, 1921: 2" Concrete with (illegibly?) center 20" E & W. corner is exactly in center of pavement-tile 4" S 69"K 48.2", Elm 6" N 89"W 64.4", Gas Pipe East 23.25' & Nest 24.95'. CSR 2/318: G.F. DeLaMater, 1956: Copper tack in 2" Square Coder plug in Concrete Pavement. LCR 1/47: M.M. Wakerhut, 1972: Found 4" Iron 3" down, spx f & P. Pole N 50°E 31.64", spk P.Pole N 35°W 30.51'. Misc.: C.I. Robinson, 1988: Removed Diseage County Monument while construction 50" Storm Sewer crossing. Set PK nall in centerline of Pavement North 33.13', Nakenhut's witnesses undisturbed. Set PK nall in corner in 1990 because N. Center Street was proposed for reconstruction. This was removed in 1994 during construction and not replaced. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monument in corner from Wakenhut's T & P Pole NE, ½" iron rod east 33.0 (Cert. of Survey, L. 416, P.359) and measurements north & south to G-11 & G-13, respectively, proportioned to previous measurements on file in my office. C. Description of monument for corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Role S 15°E 87.13', spk P. Pole N 40°W 37.97'. OISEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, Dursuant to Act 345, PA 1990. W. Chalaman Approved by the County Survey Poor GARLAND Approved By Care By Care By	exp	ressed below:			10 - 30 - 29	282726	25-
A. Description of original monument and accessories and/or subsequent restoration: GLO 2/277; Austin Burt, 1850; Set Qr. Sec. Post-Beech 8" East 33 lks (22.0"), Sugar 8" S 64°W 29 lks (19.3"). CSR 2/322; G.F. DetaMater, 1921; 2" Concrete with (illegibly?) center 20" E & W, corner is exactly in center of pavement-Elin 4" S 87°E 48.2", Elm 6" N 85°W 64.4", Gas Pipe East 23.25" & West 24.95". CSR 2/318; G.F. DetaMater, 1972; Found 1" Iron 0.3" down, spk T & P. Pole N 50°E 31.66", spk P.Pole N 35°W 30.51". LICR 1/47; W.M. Wakerhut, 1972; Found 1" Iron 0.3" down, spk T & P. Pole N 50°E 31.66", spk P.Pole N 35°W 30.51". Misc.: C.I. Robinson, 1989; Removed Obsego County Monument while constructing 30" Storm Sewer crossing. Set PK nall in centerline of Pavement North 35.13", Wakenhut's witnesses undisturbed. Set PK nall in corner in 1990 because N. Center Street was proposed for reconstruction. This was removed in 1994 during construction and not replaced. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monument in corner from Wakenhut's T & P Pole NE, 2" iron rod east 33.0 (Cert. of Survey, L. 416, P.359) and measurements north & south to G-11 & G-13, respectively, proportioned to previous measurements on file in my office. C. Description of monument for corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01", 2" iron rod N 65°E 33.00", spk P.Pole S 15°E 87.13", spk P. Pole N 40°W 37.97". OISEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, Duzgaan to Act 345, PA 1990. W. Chalimphn OISEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, Duzgaan to Act 345, PA 1990. W. Chalimphn OISEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group. Duzgaan to Act 345. PA 1990. W. Chalimphn	NO			range, may be recorded			1
GLO 2/777: Austin Burt, 1850: Set Or. Sec. Post-Beech 8" East 33 1ks (22.07), Sugar 8" 5 64-W 29 1ks (19.31). CSR 2/322: G.F. DeLeMater, 1921: 2" Concrete with (illegibly) center 20" E & W., corner is exactly in center of payement-Elm 4" 5 87°E 88.2", Elm 6" N 89°W 66.4", Gas Pipe East 25.25" & West 24.95". CSR 2/318: G.F. DeLeMater, 1936: Copper Lack in 2" Square Codor plug in Concrete Payement. LCR 1/47" N.M. Waschut, 1972: Found 4" Ton 0.3" down, spx 1 & P. Pole N 50°E 31.66", spk P.Pole N 35°W 30.51". Misc.: C.I. Robinson, 1988: Found 4" iron in 2" square hole in old concrete, Set Otsego County Monument. Misc. C.I. Robinson, 1989: Removed Otsego County Monument while constructing 30" Store Sewer crossing. Set PK nall in center lin 1990 because N. Center Street was proposed for reconstruction. This was removed in 1994 during construction and not replaced. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Replaced Otsego County Monument in corner from Wakenbut's T & P Pole NE, ½" iron rod east 33.0 (Cert. of Survey, L. 416, P. 339) and measurements north & south to G-11 & G-13, respectively, proportioned to previous measurements on file in my office. C. Description of monument for corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, preparation to Act 345, PA 1990. No. Calcington OCtober 10, 1995		on this certificate.				33-34-1-35	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Otsego County Monument in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990. WZ 95	В.	LCR 1/47: W.W. Wakend Misc.: C.I. Robinson, in center. 1990 becar tion and a Description of corner et Replaced Otsego Count L. 416, P.359) and m	hut, 1972: Found ½" Iron 0.3' 1988: Found ½" iron in 2" so 1989: Removed Otsego County M line of Pavement North 33.13', use N. Center Street was propo not replaced. Vidence found and/or method app ity Monument in corner from Wak weasurements north & south to G	down, spk T & P. Pole N pure hole in old concret tonument while construction. Wakenhut's witnesses unused for reconstruction. Sided in restoring or reestable tenhut's T & P Pole NE. 2	50°E 31.86', spk P.Police, Set Otsego County Ming 30" Storm Sewer crossdisturbed. Set PK nail This was removed in 199 dishing corner.	onument. ssing. Set PK in corner in 94 during cons Cert. of Surve	nail struc−
Otsego County Monument in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990. 12/95 Date October 10, 1995		on file in my office	•			. • •	. • • • •
Otsego County Monument in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990. 12 95 13 00 FESSION PROFESSIONAL SURVEYOR NO. 16390 Date October 10, 1995							
Otsego County Monument in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990. 12 95 V. Chairman Date October 10, 1995				•			10:
Otsego County Monument in corner is accepted as a careful and faithful reestablishment of the position of the original corner. Spike in P. Pole N 60°E 32.01', ½" iron rod N 85°E 33.00', spk P.Pole S 15°E 87.13', spk P. Pole N 40°W 37.97'. OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990. 12 95 V. Chairman Date October 10, 1995						` .	
Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990, 1/Z/95 Date Date October 10, 1995 Approved by the County Survey Poor Group, pursuant to Act 345, PA 1990, No. 16390 Date October 10, 1995	C.	Otsego County Monumer original corner. Spil	nt in corner is accepted as a	careful and faithful ree	stablishment of the pos	sition of the .13', spk P.	154.
Group, pursuant to Act 345. PA 1990. 11/2/95						"	4, 74 1, 4
Signed by Dale October 10, 1995				Group, pursuant to Ac	inty Survey Poor t 345, PA 1990, Chairman	ROBINSON PROFESSIONAL SURVEYOR No. 16390	, E. V.
Signed by Dale October 10, 1995					A	MANAGESSIONAL	444 AND
	Sign	ned by	hinson PE & DC Otropes Country		October 10, 1995	, , <u>, , , , , , , , , , , , , , , , , </u>	

IYEYORS, JAN. ZB, 1971 REVISEO MAY 14, 1975 REVISEO JAN., 1983