DEC 0 1 1993

## OTTAWA COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Property in Sec.

Filing Requirement of Act 74, Mich. P.A. 1970

111	Ł	U	KUED
93 NOV	ł	1	AM 11: 56

RECOOR-

المرابع المتعمل المرساك	
REGISTE	م سمدة الم
REGISTE	R OF DEEDS
OTTAWA	'COLLYGEDS
,	YUUN I Y MI

For corners in			
Ottawa	Located In:	Corner Code ≠	
(County)	Jamestown Township		

T <u>5N</u> R <u>13W</u> 1. Public Land Survey T \_\_\_\_\_ R \_\_ T \_\_\_\_\_ R \_ T \_\_\_\_\_ R \_\_ 2. Property Controlling \_\_ T \_\_\_\_\_ R \_ S \_\_\_\_ T \_\_\_ R \_\_ S \_\_\_ T \_\_\_ R \_\_ in Section Miscellaneous


\_\_ T \_\_

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5	Private Claims

I. Rodney D. Unema , in a field survey on October 22 \_ . 19 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

K-4 1/4 corner between Sections 11 and 12

K-4 1/4 Corner between Sections II and 12					
L.C.R.C. Liber 5, Pg. 349	L.C.R.C. Liber 2, Pg. 299	L.C.R.C. Liber 1, Pg. 325			
(Dec. 1988)	(September 1973)	(April 1972)			
Cast iron Mon. in Mon. Box.	RR Spike	Iron in Mon. Box			
C/L stop sign WSW 43.20'	St. sign N90°E 19.65'	Nail in sde P.Pole SE 62.34'			
PP SW 74.22'	CP pole S35°E 62.30'	Nail in sde P.Pole SW 59.49'			
PP SE 62.34'	CP/MBT pole S40°W 59.50'	W edge St. sign post E 19.53'			
12" Elm E 58.93'	51711B1 pore 516 # 55465	SE cor. barn NW 152.39'			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-4 Found Ottawa Co. C.I. Mon. in Mon. Box 2" below pavement at intersection of 8th Avenue and Greenly. Found nail in S sde 14" Elm N84°E 58.93 Found nail in NE sde P.Pole \$34°E 62.22

Found PK nail in SE sde P.Pole S45°W 74.28'

Accepted as a careful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 1/4 corner between Sections 11 and 12

. Cast iron Mon. in Mon. Box 2" below pavement surface

On C/L of N-S BT road (8th Avenue)

Surveyor's Michigan License No. \_

C/L of BT road to West North 3.0'

74.27 S45°W

O.C. tag & nail in SE sde P.Pole O.C. tag & nail in NE sde P.Pole O.C. tag & nail in S sde 14" Elm S34°E 62.20 N84°E

58.93 C/L 3" dia. street sign pole N28°W 65.781

O.C. tag & nail in E sde P.Pole NO8°W 259.32' (E.D.M.)

Inema! Signed by \_

November 4, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

RODNEY D.

UNEMA

LAND

SURVEYOR

ESSIONAL SUP