SURVEY & REMONUMENTATION

APR 2 5 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

LAND CORNER RECORDATION CERTIFICATE Filina Requirement of Act 74, Mich. P.A. 1970 94 DEC -8 PM 12: 29

For corners in	COMMISSION	Filing Requ	irement of Act 74,
Ottawa		Located In:	Corner Code :
ıÇou	ntid.		

0t	tawa	Located In:	Corner Code ===	•		يا موسيطري مرا	2000	de ed VOTO	سک <i>ون)د</i> ۱۲۰۰ تا	ne dis NES	suce TOS	.n.)		
	(County)	Jamestown Township		5			OI	AWA	R OF COU	йŤŸ	.MI			
'. Pub	olic Land Survey	T <u>5N</u> R 13W T R T R T A	L-9	_										
⊇. Pro	perty Controlling	S T R												
in S	Section	S` T R												
∃. Mis	cellaneous	S T R		Rec	gister	of De	eds !	met?	- & l	Eita	Mire	nha	_	
Pro	perty in Sec.	S T R							pai		· · · · · ·	inei		
		Recorded Plat			. A	B C	; D	E F	G	H	ļ J	<u>к</u>	<u> </u>	М
					2	· 6	_ 5_	- -↓	-	ا . ع	2 	:		_
					3	1-4		14	\bot	4	\sqcup	_	_	_
		, in a field survey on Nov.			5	· } _ 	_ - -		_	10-	_	<u>-</u>	— 12 —	<u>. </u>
o lines	1 and 2 above were	equirements of P.A. 74, Michigan P.A in conformance with regulations a ructions of the United States Depa	nd rules therefore as rec	quired in the	6	18	-17	16	\pm	.15— 	-12	<u>-</u>	— 13	H
⊴lanager	ment or by a decree o	f a Court of Law and/or that the corn yith the rules of the Michigan Board	er points mentioned in lin	ies 3, 4 and 5	8	19	_20_	21		22.	23	,	24	

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

L-9 1/4 Corner between Sections 24 and 25

Original gov't corner set in Dec. 1831 by Sylvester Sibley Set 1/4 Section post Beech 6" 53°W 7 links Sugar 18" N24°W 23 links

expressed below:

L.C.R.C. Liber 3, Page 2 (Dec. 11, 1975) Found 1/2" round iron T.Pole (PK in W side) N 21.10' P.Pole (PK in E side) S 52.71' NW 165.32' SW corner garage

13

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2 solid iron (bent) \pm on C/L of E-W gravel road Held base of bent 1/2" iron by existing witnesses. Found nail & bottle cap in E side T.Pole Found nail & bottle cap in E side P.Pole North 21.10' South 52.74' N42°W 165.32' SW corner garage (brick)

Accepted position of 1/2" iron (base) as a careful perpetuation of the position of the original corner and replaced with Std. 0.C. Cap on $24" \times 3/4"$ iron rod.

P.A. 345 OTTAWA COUNTY PEER APPROVED

C. Description of monument for corner and accessories established to perpetuate localing L-9 1/4 Corner between Sections 24 and 25 Std. O.C. Cap on 24" x 3/4" iron rod

Top of cap is 6" below gravel surface SW corner of garage (brick)
Set nail & O.C. tag in E side T.Pole N42°W 165.32' 21.10' North Set nail & O.C. tag in N side 24" Walnut S78°E 123.16' Set nail & O.C. tag in E side P.Pole South 52.74' Fence lines to South and North

OF MICH RODNEY D UNEMA LAND SURVEYOR 33987 SSIONAL SUR

REVISED MAY 14, 1975

REVISED JAN., 1983

	" MANNETS".
Signed by Kodne D. Unema Date	Nov. 17 1994
Signed by ROTHE D. When Date	1001011117
33987	
Surveyor's Michigan License No	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971