OTTAWA COUNTY REMONUMENTATION

93 HOV -8 PM 1:53

LAND CORNER RECORDATION CERTIFICATE

Dhydie Caldyan REGISTER OF DEEDS

For corners i	in		Filing Requi	Corner Code ##	1970	*	OTT	AWA	ĊÕU!	ĬŤŸ,	ΗĪ		
(County)		-	Located III.	Contai Code 222									
1. Public La	and Survey	•	7 <u>5N</u> R <u>16W</u> T R	G-4 (W 1/4 Sec 10) Park Twp.									
 Property in Section Miscellar Property 	neous	s	T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R T R R T R		Regis	ster of D	eeds S	Stamı	o & F	ile N	lumi	ber	
4. Lot No.	, Re	corded F	Plat			АВ	C D	E F	G	Н 1	j	K L	L
5. Private C	laims					2	ŤŤ	Τ	T		T	T	T
						3 4	5-	1		3-	-2- - -		1
, David R. Greer , in a field survey on September 15 , 19 93								1 1		i			12-
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:						5 6 - \(\)8 - \(\)7 8 - \(\)9 9 - \(\)10 - \(\)30 - \(\)11	-20-	21-		22	14- 23- 26-		13-24-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.							32-	33	+	34	35- 35-	 	 -36-
A. Descript	tion of original m	onumen	t and accessories a	nd/or subsequent restoration:		13						-	-
G-4			Dec. 8, 1972	Recorded in Liber 5 Page 11	14, June	27, 1 984	ŀ						
28"	nd monument box Catalpa L Polo	SE SE	80.82'	Cast Iron Monument 15" Sassafras Tolo Polo	ESE	64.91							

Power/Light Pole

Tele. Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Power Pole

Found cast iron monument and accepted it as a careful and faithful perpetuation of the position of the orginal corner

42.67

15" Sassafras 64.91" Tele Pole 76.39 SE Tele Pole NW 43.23'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found broken C.I.M. in monument box Set O.C Monument Iron & Cap

AZ - Michigan State Grid Direction

CL top of hydrant AZ. 140°03' 49.97 O.C. Remon tag & nail in SE Side Power Pole 42°50' 38.19' AZ. O.C. Remon tag & nail in SW Side 10" Pine AZ. 316°54' 70.81 Found P. K. in East Side of Power Pole AZ. 194°10' 138.84'

NE

41.58

43.23'

SURVEYOR 16042

DAVID R.

GREER LAND

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

Surveyor's Michigan License No.

16042