SURVEY & REMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 AM 10: 02

COMMISSION

Chylles Radionan For corners in REGISTER OF DEEDS OTTAWA COUNTY, MI Ottawa. Located In: Corner Code ## T __5N R _16W 1. Public Land Survey I-6 (W1/4 Cor Sec 14) ____ R ____ Park Twp. _ R _ T _____ R __ 2. Property Controlling __ T _____ R ____ in Section S ____ T ___ R ____ S ____ T ___ R ____ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat __ 5. Private Claims _ 3 John P. Clapp November 29 , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: 1-6 1-6 Govt Land Office Survey Notes Recorded in Liber 1 Recorded in Liber 6 1832-Surveyor, Calvin Britain Page 229, Jan 11, 1972 Page 173, Oct 11, I991 Set 1/2 Mile Post Set Cast Iron Monument Reset CIM from previous ties 16" Pine N59 1/2°W 15 links 12" Oak SW 52.80' 20" Oak ΝE 52.48' 16" Pine S59 1/2°E 8 links 12" Pine W 45.18' 13" Ash NW 40.69' **Power Pole** SE 58.67 30" Oak SE 72.77 20" Oak SE 72.07 17" Tw Oak SW 50.40' 16" Oak NE 51.57 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: **I-6** Found cast iron monument in monument box and accepted it as a careful and faithful perpetuation

of the position of the original corner

Found Nail in SE Side 17" Twin Oak AZ 219° 50.34 Found Nail in NE Side 16" Ash AZ 307° 40.70 Found Nail in NW Side 28" Oak AZ 42° 52.42' Found Nail in E Side 12" White Pine AZ 272° 45.02

PEER APPROVED_12

50.42'

51.83'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Cast Iron Monument in Monument Box

O.C. Remon Tag & Nail SE Side 17" Twin Oak AZ. 219° O.C. Remon Tag & Nail SW Side 19" Oak AZ. 137°

O.C. Remon Tag & Nail NW Side 28" Oak AZ. 42° 52.69 AZ. 307° 40.68

O.C. Remon Tag & Nail NE Side 16" Ash

Date Dec 2, 1994

Signed by John P. Clapp Surveyor's Michigan License No. __14091

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

OF MIC

JOHN F

CLAPF

Surveyo

REMON LIBER 2 PAGE 102

W:\Docs\Surv\Remon.doc