## SURVEY & REMONUMENTATION

APR 2 4 1995

Ottawa County Remonumentation

RECORDED

LAND CORNER RECORDATION CERTIFICATE

94 DEC 14 AN 9: 41

For corners in COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

Profestion and Esternant

Ottawa (County) REGISTER OF DEEDS OF TAWA COUNTY, MI Located In: Corner Code ## 1. Public Land Survey T \_5N R 16W K-13 SWCor\_ T \_\_\_\_\_ R \_\_\_ Sec 36 T \_\_\_\_ R \_ Park Twp. T \_\_\_\_ R \_\_ 2. Property Controlling \_ T \_\_\_\_\_ R \_\_\_ \_\_ T \_\_\_\_ R \_\_ in Section 3. Miscellaneous \_\_ T .\_\_\_\_ R \_\_ Register of Deeds Stamp & File Number Property in Sec. \_\_\_ , Recorded Plat \_ 5. Private Claims \_ \_ , in a field survey on . November 18 do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: K-13 Recorded in Liber 5 K-13 Govt Land Office Survey Notes K-13 Recorded in Liber 4. Page 309, Mar. 18, 1988 1832-Surveyor, Lucius Lyon Page 43 Mar 17, 1980 Iron in Mon. Box Set Post Fd Iron in Mon Box CL Hydrant NE 53.17 15" Beech N52 1/2 °E 21 links 92.33' NW Cor St Hse SE 116.65 NW Cor Bk Gar S 24" Beech N41 °W 47 links N35°E 53.16' NW Cor Brk Gar 92.33' CL Hydrant S N70°W 80.82' SE Cor Blk Fnd NW 80.891 SE Cor Hse S50°W 52.61' Iron 75.05 Power Pole W 52.61 sW Power Pole B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found iron pipe in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner SE Corner House Foundation N65°W 80.85 Allegan County Corner 75.08' P.A. 345 OTTAWA COUNTY PEER APPROVED\_12/12

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13

Set O.C. Remon Iron and Cap in Monument Box

NE Corner House, Brick 95.07 AZ.166°46' NW Corner House, Foundation 189,92' AZ.247°09' SE Corner House, Foundation 80.85 AZ.295°42' O.C. Remon Tag & Nail SE Side 18" Maple AZ. 54°53 159.77

Allegan County Corner AZ.270°09'51" 75.08"

Signed by John P. Clapp Surveyor's Michigan License No

W:\Docs\Sun\Remon.doc

REMON LIBER 2 PAGE 56