SURVEY & REMONUMENTATION

APR 2 4 1995

For corners in

COMMISSION

9" Hemlock N25°E 17 links

10" Hemlock S25°W 18 links

NOTE: Additional recordings

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 AH 10: 03

Dhythis Bollman

	Ottawa Located In		n: Corner Code ##			OTTAWA COUNTY, MI							
۱.	Public Land Survey	T	R R	L-3 (N1/4 Cor Sec 12 Park Twp.	2)								
2.	Property Controlling in Section	S T S T	R										
3.	Miscellaneous	s T			Dagial	er of D	andr C	lama	9. Ei	la N	umt	ar	
٠.	Property in Sec.	S T			negisi	er or De	eeus o	samp	Q (FI	IC IV	until.		
	,,opo,												
4.	Lot No,	Recorded Plat				A R	c n	E F	G F	a L	J	K I	_ 1
5 .	Private Claims		···					Ť	ŤŤ	- 	Ť	T	Т
			•	-	;	2 6	_ 5	— <u>4</u> —	 -3	· —	-2-	+-	1-
						3	\vdash		╂─┼	\dashv	+	-	φ-
	John P. Clapp	, in a field survey on	Nove	ember 29 19 _ 94	•	4 7	8 	 	iċ	3	1'1- 		12-
, ~ do	hereby certify that under re	equirements of P.A. 74, N	tichigan P.A. of t	970, the corner points mentions	ed .	618		1	\prod_{i}	$oxed{oxed}$			13-
n I	ines 1 and 2 above were	in conformance with re	gulations and re	ules therefore as required in the	ne	7 0		ľ	Τï		Ï.		Ĺ
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5											7		24
abo	ove were in conformance v	vith the rules of the Mich	igan Board of La	and Surveyors or by a Decree o	a	8 —19— 9	20	21	Ti		-23- 	Т	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as							\Box				丁		
	ressed below:					030	29-	2B	1-2	7-1-	26- 		25
NO	TE: Not more than 4	corners, all in the sa	me town and i	range, may be recorded	1	1			† †		+	t	+
	on this certificate	B.			1	2 3 1	32-	-33-	 -3¦	4	—3 ['] 5-		3 6 -
					1	3	Щ						
٩.	Description of origina	I monument and acce		r subsequent restoration:									
	L-3		L-3		L-3			_					
		fice Survey Notes				rded in							
	1832-Surveyo	or, Calvin Britain	Page 15, M	lay 4, l971	Page	79, Se	p 22,	1971					
	•		Ed 4" Iron D	Dina	E4 4"	Iron D	ina						

NNE

MNW

SSE

SE

90.66"

118.63'

84.62"

111.88'

on reverse side Liber 5, Pg 148

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

46" Maple

10" Cherry

6" Cherry

12" Oak

Found cast iron monument in monument box (top missing) and accepted it as a careful and faithful perpetuation of the position of the original corner

Found P.K. SW Side Power Pole AZ 331° 53.25′
CL Street Sign AZ 222° 42.83′
Found Nail in SW Side 12" Bl. Cherry AZ 112° 85.22′
P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/12/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3
Found Cast Iron Monument in Monument Box (top missing)
O.C. Roman Tag & Nail in NW Side 12" Twin Ring. AZ

O.C. Remon Tag & Nail in NW Side 12" Twin Pine AZ. 52° 178.95'
O.C. Remon Tag & Nail in SW Side 18" Oak AZ. 141° 112.66'
O.C. Remon Tag & Nail NNW Side 5"Ornamental AZ. 236° 60.17'
O.C. Remon Tag & Nail NE Side 10" Oak AZ. 321° 85.83'

Signed by John P. Clapp

Surveyor's Michigan License No. 1

Dent Claps

Date Dec 2, 1994

CLAPP
LAND
SURVEYOR
NO.
14091

90.66'

118.63

84.62'

111.88'

NNE

NNW

SE

SSE

46" Maple

10" Cherry

6" Cherry

12" Oak

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

REMON LIBER 2 PAGE 126

L-3
Recorded in Liber 5, Page 148
June 27, 1984
Found 1" Iron & Angle Iron
Set Cast Iron Monument
Power Pole NW 53.45'
Street Sign SW 42.90'
Twin 8" Maple SE 70.77'
11" Cherry ESE 85.26'