SURVEY & REMONUMENTATION

APR 2 4 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 AM 9: 41

Servicial Cartinean

For corners in

REGISTER OF DEEDS OTTAWA COUNTY, MI Ottawa (County) Located in: Corner Code ## T 5N R 16W M-3 (NE Cor Sec 12) Public Land Survey ___ R _ Park Twp. R. **Property Controlling** T _ in Section _ T Miscellaneous Register of Deeds Stamp & File Number Т Property in Sec.

4. Lot No. ______, Recorded Plat _______

5. Private Claims _____

John P. Clapp , in a field survey on November 29 , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

	W-3 Recorded in Liber 1, Pg 75			IAI-O		
M-3	Sept 22, 1971 Fd Boat Spike			Recorded in Liber 5,		
Govt Land Office Survey Notes	Tele. Pole	SW	55.84'	Page 148, June 27, 1984		
1832-Surveyor, Calvin Britain	St Sign	SW	41.20'	Fd Spike over iron pipe		
10" Aspen N52°W 1.89 ch	Tele. Pole	NE	82.73'	Set cast iron monument		
10" Aspen S29°W 2.23 ch	20" Maple	NE	70.15'	Power Pole	SW	50.50'
	Tele Pole	SE	124.96'	26" Maple	NE	70.24'
	SE Cor Gar	ИW	108.09'	Light Pole	NW	44.67'
•	Holland Cor	N	25.68'	Holland Cor	N	25.64

M.2 Decorded in Liber 1, Da 75

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-3

Found cast iron monument in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner

CL Street Sign AZ 215° 45.35' Found Nail SW Side 30" Maple AZ 58° 70.18 SE Cor Attached Garage 108.09 AZ 312° Holland Twp Corner 25.69' Nail & Tag SE Side Power Pole AZ 210° 50.51' 44.88 P.K. SE Side Light Pole AZ 332°

P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/12/94

10

12

14-3

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3

Found Cast Iron Monument in Monument Box 71.22 O.C. Remon Tag & Nail NW Side 30" Maple AZ. 58° "X" NE End 18" Concrete Culvert AZ. 126° 50.42 O.C. Remon Tag & Nail SE Side Power Pole AZ. 210° 50.54' O.C. Remon Tag & Nail NE Side 12" Quad Maple 309° 71.40' AZ. 25.69' Holland Township Corner

JOHN P.
CLAPP
LAND
SURVEYOR
NO.
14091

Signed by John P. Clapp

Surveyor's Michigan License No. (1409)

Date <u>Dec. 2, 1994</u>

FORM APPROVED BY MICHIGAN STATE BBARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAH., 1983