SURVEY & REMONUMENTATION

APR 2 4 1995

For comers in

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

RFCORDED

94 DEC 14 AM 9: 42

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

Doly the Chliman

Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY. MI
Public Land Survey	T -5N- R 16W T R T R T R	M-6 E1/4 Gor Sec 13 Park Twp.	
	S T R		
	S T R		
	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No , Reco	orded Plat		
5. Private Claims			A B C D E F G H I J K L M
			3 3 2 3 3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3
			4 - 7 8 9 10 11 12 1
i, John P. Clapp ir do hereby certify that under require	5		
in lines 1 and 2 above were in co			
current manual of survey instruction			
Management or by a decree of a Co	· · · · · · · · · · · · · · · · · · ·		
above were in conformance with the Court of Law; established, re-e			
expressed below:		Todayaran Todaya	10 30 29 28 27 26 25
NOTE: Not more than 4 corn	11		
on this certificate.			12 31 32 33 34 35 36
A. Description of original mor	nument and accessories and	I/or subsequent restoration:	13
· M-6	M-6		M-6
Govt Land Office Survey Notes Recorded in Liber 5			Recorded in Liber 5

1832-Surveyor, Calvin Britain	Page 112 June 27, l984		Page 154, Oct 29, 1984			
Set 1/2 Mile Post	Fd Iron Pipe, Set CIM			Set Cast Iron Monument		
8" Beech is Post	Holland Cor	N	18.16'	Holland Cor	N	18.18'
	Power Pole	ENE	29.92'	Tw 12" Oak	Ę	57.92'
	17" Beech	SE	92.05'	15" Oak	WSW	61.10'
	13" Oak	WSW	61.28'	4" Poplar	WNW	61.54

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found cast iron monument in concrete in pavement and accepted it as a careful and faithful perpetuation of the position of the original corner

Holland Township Corner 18.18' **CL** Hydrant AZ 44° 45.83' **NW Cor Porch Foundation** AZ 115° 77.80'

PA. 345 OTTAWA COUNTY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Cast Iron Monument in Concrete in Pavement

O.C. Remon Tag & Nail SW Side 18" Beech AZ. 92.22' 148° **NW Corner Garage Foundation** AZ. 229° 140.69' O.C. Remon Tag & Nail SW Side 12" Pine AZ. 78.52' 317° O.C. Remon Tag & Nail NW Side 14" Pine AZ. 55° 100.48

John P. Clapp

Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983

CLAPF LAND

14091

RED LAND