SURVEY & REMONUMENTATION

DEC 01 1998

Surveyor's Michigan License No.

SECTION		TAWA COUNTY RI CORNER RECOF					
020:10:	Filing	Requirement of	Act 74, Mich.	P.A. 1970			
For corners in	-	•	·			- (5	
Ottawa(Located In:	Corne	er Code ##	1	RECORDE	.U	
(County)	Georgetown 7	Γownship <u> </u>					
Public Land Survey	т <u>б</u> N R)	98 J	UL 24 PH	1:46	
1. Public Land Survey	T R	NW Co	or.	•			
	T R		2	,	Pary with	II.	
	T 7N R	13W II-1	3	1	any with	rene	
2. Property Controlling	S T R				REGISTER OF DITTAMA COUNT	F F D D	
in Section	S T R			· ·	31 thesaw		
3. Miscellaneous	S T R			Register of E	eeds Stamp	& File Number	
Property in Sec.	S T R						
4. Lot No, R	ecorded Plat			A 8	CDEF	сн Д Ј К	Ł
5. Private Claims							T
				- [† 5 † - f	1 3 - 2 - 1 -	- 1
				3	1 1 1	 	†
Dodoou D. Haasa		M 21	0	。 ⁴├─ <i>┆</i> ─	 	1-10-11-1	-1) -1
Rodney D. Unema do hereby certify that under req	, in a field survey on $_$	higan P.A. of 1970, the	corner points men	S, 5	 	 	†
in lines 1 and 2 above were in	conformance with regu	lations and rules the	refore as required	in the 6 -18-	17-16-	15 14-	-1: 1
current manual of survey instru	uctions of the United Sta	tes Department of the	Interior, Bureau o	of Land 7	+	 	+
Management or by a decree of a	a Court of Law and/or that	the corner points me	ntioned in lines 3, 4	4 and 5 8 19	20 21	22 23	-2
above were in conformance wit Court of Law; established, r	n the rules of the Michiga e-established - monume	an Board of Cano Surv nted = re-monumentes	reyors or by a Deci d recovered, fou	ind as	+	 	+
expressed below:	e established, monamo	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	1030	29 28	27-26	-2
NOTE: Not more than 4 co	orners, all in the same	e town and range, r	may be recorded	d 11	+	╽┈╽┈ ┩┈╂╴	4
on this certificate.			-	1231	32 33	34-35	-3
				13			┙
A. Description of original r	monument and access	ories and/or subse	equent restoration	n;			
T_1	1	•					
Common corner with I-13, T7N R13W per G.L.O. not map. Nov. 1831	L.C.R.C	., Liber 2, Page : 973 - Vankóoten	213	Ottawa Co. Road	Comm. Wits.	Iron	
T7N R13W per G.L.O. not	es & June, 1	973 – Vankóoteň		Spike in 12" Elm Spike in 6" Ash	l E	30.25'	
POST.	1 201Ke 1	n Tw. 14" Elm n 16" Elm	W 19.60'	Spike in 18" Elm Spike in 6" Hick	NĒ SE	33.8'	
6" Hickorv N48°E 16 Li	nks Spike i	n 16" Elm	E_ 34.07'	Spike in 6" Hick Spike in 12" Elm	ory NE NE	8.1 30.4	
7" Hickory N58°W 20 Li	nks Spike ii Spike ii		' NE / 35 SW 5.85'	Spike in iz Emi	i NL	JU+4	
	J	, 5	011 0100		(OVER)		
			į		(OVLIV)		
	•						
B. Description of corner e	vidence found and/or	method applied in	restoring or rees	stablishing corner:			
I-1				·			
Found 3/4" Iron Pipe on P No remaining witnesses w	Peninsula of land						
No remaining witnesses we	ere found due to ear	th work and lands		P.A. aas	ATTOMAL .		
etc. around corner. Loca measured in 1977 and 1979	9 in Sec. 2–6–13 and	I Sec. 35-7-13 by	Exxel	PETO A SUSSE	OTTEMA	ANIMITY	
Engineering.		0	•	PERE APPRION	10 (n-	1-90	
Accepted as a careful and	d faithful pernetuat	ion of the mositi				LIQ	
Accepted as a careful and the original corner, and on 3/4" X 36" steel bar.	replaced 3/4" Iron	with standard Ott	tawa County cap	,	19.10). ?/ /	_
on 3/4" X 36" steet bar.		,					
				*Over f	or sketch		
		•		010, 1	or site out		
C. Description of monume	ent for corner and acco	essories establishe	d to perpetuate	locating the position	n of the corញ្ញ	Time.	
C. Description of monume	sill for conter and acco	33301703 33143.1211		•		4 HICHICAN	
I-1	9 Ct 1 D				المرابا المحو	- G 14	Ĺ.
Ottawa County Cap on 3/4' Set Nail & O.C. tag in F	"Steel Bar side 14"Ash	N10°W 39.26	ń'		# 5/ of	DNEY D.	٩
Set Nail & O.C. tag in E Set Nail & O.C. tag in N Set Nail & O.C. tag in S Set Nail & O.C. tag in S Set Nail & O.C. tag in W	E side 12" Äsh	ŊġŏśŴ ĭġ.ā́	Š'		₹*/ KU	UNENA TE	
Set Nail & O.C. tag in S	Side TZ" Uak Side 6" Cottonwood	N90°W 35.17 S0°F 19.4	£'.		# * i	LAND 12	١
water's edde	DIGG G GOODINGOOD	EdSt. 3	-		1 × S	URVEYOR 3	<u>,</u>
Water's edge		ŠŠŠ°W 3 4 ♥			1 \	NO. 33987	ij
Corner is common with I-	13, T7N, R13W				Por		r
	•				POFESS	ONAL SURVEY	
					- MANA	WWW. Side	
		/				•-	

SURVEY & REMONUMENTATION

DEC 01 1998

SECTION

Act 132 Survey
Exxel Engineering, Inc., May, 1977
3/4" Iron
Spike in Face Twin 16" Elm E 34.07'
Spike in side Twin 6" Ash NE 7.38'
Spike in side Twin 12" Oak SW 58.52'
Spike in side Twin 14" Oak S 47.09'

