## SURVEY & REMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

94 DEC 14 AM 9: 43

	riing kequ	frement of Act 74, Mich. P.A.	1970	Dollar.	11	72	100	>	
For corners in OTTAWA	t mankad ta	00-4	~ <i>l</i> -c	RE	GISTE	R OF	DEED	S	
(County)	Located In:	Corner Code ##		01	'TAWA	COUN	ITY. Y	1[	
Public Land Survey	T R T R T R	Georgetown Twp							
in Section S	T R T R T R								
	: T R		Register o	Deeds	Stam	2 & F	ile N	umbe	r
Property in Sec. S	i T R				······································				
i Lot No	rded Plat					_			
			— <u>^</u>	B C D	E F	<del>-</del> G-		<del></del>	Τ'
3. Titulo Gianno			2	╌┼╌┇╴			3-	-2-	<u> </u>
			3		<del></del>		$\vdash$		
Bandal I Wantergen	Decen	mber 6 94	4_	, —   <sub> </sub>	_ <b> </b> _  -	<b>—</b> 1	<u> </u>	-⊹	12
	a field survey on	, 19	., 5				╀		
io hereby certify that under require	ments of P.A. 74, Michigan P	A. of 1970, the corner points mentione	ed 6 1	8	16	<b>-</b> ↓-1	5	-14	13-
n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					$\rightarrow$		<b> -</b>  -		
Annagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			15 81	9——20	21	<u> </u>	22-	_23	24-
bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as			ia 9				$\sqcup$	$\bot$	
Court of Law; established, re-established, re-	stablished, monumented, r	e-monumented, recovered, found a			1 29	Щ,	ļ	_26	25-
			11	֓֞֞֞֓֞֓֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	Ĩ		Ï	Ĩ	
IOTE: Not more than 4 corne	ers, all in the same town	and range, may be recorded	12			Т.			١
on this certificate.			13	1———32 	33		ï	-35	1
Description of original mon	ument and accessories	and/or subsequent restoration:	13	l I	1 1				
1831 - Lyon & Sibley	Liber 2, I		1						
Set H.M.P.	Boat Spike	e	Ì						
Beech 10" N45E 27 Links	Centerlin	e B.T. West 2.3'	ĺ						
Sugar 6™ \$58₩ 19 Links	Nail in s	ide P. Pole NW 62.36'							
	Nail in s	ide Triple 12" Box Elder SSW	1						
	113.72		1						
	1								
	1	-	1						
	1		1						

Description of corner evidence found and/or method applied in restoring or reestablishing corner:
K-10 Found boat spike in mon box 3.4' East of centerline 8th Avenue and accepted as a careful and faithful

perpetuation of the position of the original corner

Centerline B.T. West 3.4' Nail in side P. pole NW 62.32' Nail in side Triple 12" Box Elder SSW 113.72

345 OTTAWA COUNTY

Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-10 Removed boat spike, set 3/4" X 36" solid bar with Ottawa County Remon Cap

AZ = Michigan State Grid Direction

Set Ottawa County Remon Tag & Nail in E side Triple 14" Box Elder AZ. 194 deg 112.93'

Top Hydrant AZ. 153 deg 60.09'

Set Ottawa County Remon Tag & Nail in NW side 14" Maple AZ. 31 deg 46.69'

Set Ottawa County Remon Tag & Nail in S side P. pole AZ. 313 deg 62.32'

ATEOF MICKING /UGTEVEEN SO LAND SU

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983