- SURVEY & BEMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION	CO	M	MIS	S	ON	į
------------	----	---	-----	---	----	---

LAND CORNER RECORDATION CERTIFICATE 91, DEC 14	WHO: 03
Ciling Paguiroment of Ast 76 Mich D & 1070	

_	00141841100101	Filing Require	ment of Ac	ł 74, Mic	h. P.A.	1970		/		
For co	rners in					1970 Dalipur	LU KA	and the state of t	,	
—Ot	tawa (County)	Located In:	Corner C	>ode ≠		A REI	GISTER OF TAWA COL	MYYTMI		
					ŀ	31	.,		.,	
1. Pu	iblic Land Survèy	T 6N R 16W	- I-2 W1	/4 Cor	-					
		T R	Sec 2		-					
		T R	-Port Si	heldon T	wb.					
		T R			- "					
		TR			-			•		
	Section S	S T R S T R			-					
_		; r r ; T R			-	Register of D	eeds Sta	mp & File	Number	r
F11	operty in Sec. S	· · · · ·				······································				
4 10	t No Reco	rded Plat								
						· A B	CDE	F G H	I J K T T	
•						2 - 6-	┿╌	- 4	6 -2-+	—
						3			 	
						4 - 17-		- 9	 	
i,Jo	hn P. Clapp in	a field survey onDe	cember 3.	, 19	94	. 5	1_1_1.			
		ments of P.A. 74, Michigan P.A.					17-1-	-1615	 	
		nformance with regulations and ins of the United States Depart				_1 1	الثا			
		urt of Law and/or that the corner						21-22-	23-	
-	· · · · · · · · · · · · · · · · · · ·	e rules of the Michigan Board o				13	20	21		,
	· · · · · · · · · · · · · · · · · · ·	stablished, monumented, re-m	onumented, i	recovered,	found a	s				
expres	sed below:					10 -30-	29-	-2827	 26 	
NOTE:		ers, all in the same town an	d range, may	/ be recor	rded	11		 	+++	
	on this certificate.					1231	32	-3'33'4	35-	<u>-</u> -:
						13			1 1 1	
A. De	escription of original mon	nument and accessories and	vor subsequ	ent restor	ation:					
	I-2 Govt Land Office	ce Survey Notes I-2	Recorded	in Liber	1,	I-2 Recorded	d in Libe	er 4		
	1832-Surveyor, Ca		Page 679, Oct 13, 1972 Page 679, Oct 13, 1972			Page 162, A	Page 162, April 1, I981			
	Set 1/2 mile post		und Iron Pi			Fd. Iron, Set	•		ment	
	6" Hemlock N69°E		Sassafras	•	39,96'	Power Pole	NW	69.75		
	3" Hemlock S19°V		" Maple			T. Pedestal	SW	39.71'		
			St. Sign			Power Pole	NE	56.40'		
	See reverse side fe		" Maple			31" Maple	SE	60.00'		
		66 & L.5, Pg 289 12				or mapio	· ·	00.00		
	-	_	•							
B. D	escription of corner evide	ence found and/or method a	applied in res	toring or	reestabli	shing corner:				
		,	<u>.</u>	1				NITV		
	. •	11 1 0-11	" 1 . []		P.A.	345 OTTAW	A COU	10 (
		Keeding O. Pla	desoele	, PCL	n ADE	345 OTTAW ROVED/	2/12	194		
	I-2	. /		PEE	H MET	1104-0		7		
		onument and accepted	it as a care	ful and	faithful	pernetuation	of the r	osition o	f the	
	original corner	one and and adopted	40 4 0410		ain ii Mi	hai haraanan	3. a.o. þ			
	CL St. Sign		AZ 13	go	41.22'					
		in SM Side Bower Bele								
	-	in SW Side Power Pole			69.71'					
	CL Telephone Ped		AZ. 22		47.86'					
	-	in NW Side Power Pole			56.39					
	Found Nail & Tag	in ENE Side 32" Maple	AZ. 1	54°	59.96'					

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-2 Found Cast Iron Monument in Monument Box O.C. Remon Tag & Nail in SE Side Power Pole 36° 56.47' **NW Corner Garage Foundation** AZ. 142° 238.49' O.C. Remon Tag & Nail in N Side Twin Oak AZ. 250° 96.67' SE Corner House Foundation AZ. 332° 158.56'

Signed by John P. Clapp Surveyor's Michigan License No. 14091

W:\Docs\Surv\Remon.doc

I-2
Recorded in Liber 5,
Page 66, Sept 22, 1983
Fd. Cast Iron Monument
Power Pole
NE
56.39'
30" Maple
SE
59.95'
T. Pedestal
SW
39.57'
Power Pole
NW
69.71'