FEB 2 4 2000

RECORDED

99 OCT 27 PM 1:49

SECTION

Surveyor's Michigan License No.

Ottawa County Remonumentation LAND CORNER RECORDATION CERTIFICATE

For corners in	H P Contract to the	Filing Requirement of	Act 74, Mich. P.A. 1	970 Sam Sallen
Ottawa		•		REGISTER OF DEEDS
(County)	Located in:	Corner Code #		United to the Party of the Part
•				
1. Public Land Survey	T <u>7N</u> T T		mer, Section 8 the Township	
Property Controlling     in Section     Miscellaneous     Property in Sec.				
			<del>-</del> L	Register of Deeds Stamp & File Number
4. Lot No, Re 5. Private Claims	ecorded Plat		····	ABCDEFGHIJKLI
				2 - 6 - 5 - 4 - 3 - 2 - 1 -
I, Maurice J. Rosema	, in a field survey	on <u>Oct. 16</u> , 19 <u>99</u> d	io hereby state that under	3 9 10 11 12
requirements of P.A. 74, Mic conformance with regulations United States Department of that the corner points mentic Board of Land Surveyors o recovered, found as expresse	chigan P.A. of 1970, the case and rules therefore as recathe interior, Bureau of Laroned in lines 3, 4 and 5 about 5 by a Decree of a Cou	comer points mentioned in line juired in the current manual of id Management or by a decree over were in conformance with	es 1 and 2 above were in survey instructions of the of a Court of Law and /or the rules of the Mishings	5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			8 -19 -20 -21 -22 -23 -24 -	
on this certificate.				10 30 29 28 27 26 25
				11 12 31 32 33 34 35 36
A. Description of original C-4	monument and access	sories and/or subsequent r	estoration:	13
GLO - 1838 R. Whitcomb D.S. Set post	LCRC per Liber (Clapp - 1974) 1" gas pipe	2, Page 523		LCRC per Liber 5, Page 336 (Rosema - 1988) C.I. monument
12" Beech - N661/2°W 8 links	24" Oak - SSW 7 12" Oak - NW 30			Nail in W side 24" Oak - SSW 8.62'
8" Beech - S25°E	fence to east	.03		Nail and tag in SW side 12' Maple - NW 31.05'
25 links				Nail and tag in NW side 4" Maple - NE 12.54'
B. Description of corner of C-4	evidence found and/or	method applied in restorin	g or reestablishing corn	ner:
Found Cast iron monum Found nail and tag in W	side 24" Maple - Si	23°W 8.62'	<b>)</b>	165 OTTAMN 1977Y
Found nail and tag in SV Found nail and tag in W	V skie 24" Maple - I side "dead" 4" tree	N42°W 31.14' - N25°E 12.54'		10/18/99
	DATO GOME 4 HCC	- 176J E 12,J4		Mnn
				100%
hereby accept this comperpetuation of the positi	er as a correct and a on of the original o	omer.		•
C. Description of monume	nt for corner and acce	ssories established to perp	etuate locating the pos	ition of the corner OF Mo.
C-4			·	nion of the corner of MICHIGAN
ast iron monument				MAURICE J.
et nail and remonument et nail and remonument et nail and remonument et nail and remonument et nail and remonument	ation tag in W side ation tag in E side ( ation tag in SW side	24" Maple - S23°W 8.1 " Oak - N37°W 8.71' : 3" Maple - S35°F 4 6	52' 1'	ROSEMA LAND SURVEYOR NO. 27459
his comer lies on the sid	ie of a hill, on a N	S fence line, 75'± E of	f house no. 13330	POFESSIONAL SILVER
1		0		A CONTRACTOR OF THE PARTY OF TH

Date October 16, 1999